MARINE POLLUTION RISK ASSESSMENT FOR THE PACIFIC ISLANDS REGION (PACPOL Project RA1)

Volume 2: Appendices

for Marine Pollution Programme, South Pacific Regional Environment Program (SPREP)

by
Edward Anderson Marine Sciences, Sidney, BC, Canada
Brad Judson, Geolnfo Solutions Ltd., Sidney, BC, Canada
Sione Tu'itupou Fotu, Nuku'alofa, Tonga
Batiri Thaman, Institute of Applied Sciences, University of the South Pacific,
Suva, Fiji

July 2003

This report has been prepared on contract to the South Pacific Regional Environment Programme with funding from the Canadian International Development Agency, Canada-South Pacific Ocean Development Program, Phase 2.

Contract Manager:
Sefanaia Nawadra, <SefanaiaN@sprep.org.ws>.
South Pacific Regional Environment Programme
PO Box 240
Apia
Samoa

Prime Contractor:
Edward Anderson Marine Sciences
1231 Park Terrace
Esquimalt, BC
Canada V9A 4Z2

edwardanderson@shaw.ca

TABLE OF CONTENTS

1	APPENDIX 1: Contact List
2	APPENDIX 2: Database structure: Access databases and MapInfo GISA2-1
3	APPENDIX 3: Vessels, Positions and Traffic
4	APPENDIX 4: CasualtiesA4-1
5	APPENDIX 5: Risk analysis methods at the regional and EEZ scales . A5-1
6	APPENDIX 6: Sample Forms

1 APPENDIX 1: CONTACT LIST

We extend our sincere thanks to all of those who assisted with our quest for data. This contact list features people who have provided direct information on marine traffic patterns in the Pacific Islands region. Many more people contributed significantly by directing us to the eventual sources. To those we have inadvertently missed, our apologies.

American Samoa			
<u>Loftesne, Michael</u> Harbour Maritime		ph fx	(684)
Pago Pago			
<u>Carnecek, Ms Geronima</u> Polynesia Shipping Services		ph fx	(684) 633 1211
Pago Pago			
Malae, Abe Port Administration Department	Port Director	ph fx	(684) 633 4251 (684) 633 5281
Pago Pago			
Ratterman, Paul Samoa Pacific Shipping		ph fx	(684) 633 4665 (684) 633 4667
Pago Pago			
Australia			
Logan, Alistair Origin Energy	Marine Superintendent	ph fx alistair.logan@	(922) 064 00 (923) 516 50 Porigineneergy.com.au
Commonwealth of the New	hara Mariana lalanda		
Commonwealth of the Nort	nern wariana islands		() (
Malone, Michael C. Caller Box 1007 Saipan		ph fx	(670) 664 2200 (670) 664 2211
Aaron, Mitch Commonwealth Ports Authority PO Box 1007 Saipan	Assistant Seaport Manager	ph fx	(670) 322 4710
Cabrera, Antonio C. Commonwealth Ports Authority PO Box 1007 Saipan	Seaport Manager	ph fx	(670) 664 3550 (670) 322 4710
Cook Islands			
Howard, Ned Ministry of Tourism and Transport	Director of Marine	ph fx	(682) 288 14 (682) 211 91
Avarua			
Silk, Captain Don Ports Authority PO Box 84 Avatiu	Harbourmaster	ph fx	(682) 288 14 (682) 211 91 captain@oyster.net.ck

ph(691)

General Manager

Henderson, Darryll

Federated States of Micronesia

370 2386

Micronesian Petroleum Co. PO Box 400, Tofol Kosrae	96944	fx	(691) 370 2388 dhenderson@mail.fm
Fiji			
Sareem, Mohammed Beachcomber RoRo Shipping Ltd. Shed 16, Muaiwalu Jetty		ph fx	(679) 330 7349 (679) 330 7359
Whippy, Duri BP South-West Pacific Ltd. GPO Box 118, 7th Floor Vanua Hot Suva	Logistics and Planning use, Victoria Parade	ph fx	(679) 331 1622 (679) 330 0933
Hanumanthu, Carpenters Shipping PO Box 751, 5-11 Naviti St. Lautoka	Shipping Manager	<i>ph</i> fx hanumanthu.s	(679) 666 3988 (679) 66 4896 hipping@carpenters.com
Kumar, Mahendra Carpenters Shipping PO Box 751, 5-11 Naviti St. Lautoka		ph fx	(679) 666 3988 (679) 666 4896
Smith, Justin Consort Shipping Ground Floor, Dominion House, Th Suva	omson St.	ph fx	(679) 331 3266 (679) 330 3389
Probert, Harvie	General Manager and Chief Executive	ph	(679) 330 4188
Fiji Gas Co. Ltd. PO Box 548, Walu Bay Suva	Officer	fx	(679) 330 2546 fijigas@is.com.fj
Kamikamica, Captain Jone Fiji Government Shipping Service	Fleet Superintendent	ph fx	(679) 331 4562 (679) 331 2614
Suva			
Goundar, Muni Fiji Marine Safety Authority PO Box 326 Suva	Acting Principal Marine Officer	ph fx	(679) 331 5266 fimsa@is.com.fj
Savou, Viliame Fiji Sugar Marketing Corporation Suva	Senior Marketing Officer	ph fx	(679) 666 4906 (679) 666 4476 fjsugmar@is.com.fj
Bartmanovitch, Alan Forum Secretariat	Petroleum Advisor	ph fx	(679) 331 2600 (679) 331 2226 alanb@forumsec.org.fj
Suva Mavoa, Eroni Managing Director Kabara Shipping	ph	fx	(679) 330 3358
Suva			
Lee, Peter Kadavu Shipping Rona St., Walu Bay Suva	Managing Director	ph fx	(679) 331 2428 (679) 331 2987
Solo, Navu Maritime and Ports Authority Fiji	Wharf Manager	ph fx	(679) 666 5799
Lautoka			
Varea, Emosi Maritime and Ports Authority Fiji GPO Box 780, Kaunikuila House, L Suva	General Manager, Corporate Services aucala Bay Road	ph fx	(679) 331 2700 (679) 330 0064 evarea@mpaf.com.fj

Koyanasau, Donato Maritime and Ports Authroity Fiji PO Box 88 Levuka	Wharf Manager	ph fx	(679) 344 0189 (679) 344 0261
Lakepa, Captain Santini Maritime and Ports Authroity Fiji GPO Box 780, King's Wharf Suva	Deputy Port Master	ph fx	(679) 330 4998 (679) 330 0520
Macomber, Captain George Maritime and Ports Authroity Fiji GPO Box 780, Kaunikuila House, I Suva	Port Master Laucala Bay Road	ph fx gmad	(679) 331 2700 (679) 330 0064 comber@mpaf.com.fj
Kumar, Ravinesh SW Pacific Fuels Marketing - Mob Downtown Boulevard, Ellery Street Suva		<i>ph</i> fx ravinesh_kum	(679) 331 4977 (679) 330 3997 nar@email.mobil.com
Peckham, Captain Malcolm Nautical Pilots Fiji		ph fx	(679) 992 0399
Kalindole, Mosese Patterson Brothers Shipping Comp Private Mail Bag, Suite 1, Epworth Suva	Assistant Operations Manager any House, Nina St.	ph fx	(679) 331 5644 (679) 330 1562
Heathcote, Dr. Capt. Peter Secretariate of the Pacific Communication Private Mail Bag Suva	Regional Maritime Legal Advisor nity	ph fx	(679) 337 0733 (679) 337 0146 PeterH@spc.org.fj
<u>Collinge, Allan</u> Shell Fiji Ltd. Walu Bay Suva	Operations Manager	ph fx	(679) 331 3933
Yuen, Park Shell Fiji Ltd. GPO Box 168, Rona Street, Walu I Suva	Зау	<i>fx</i> Par	Terminal Manager <i>ph</i> (679) 331 3933 (679) 330 1189 k.Yuen@Shell.com.fj
<u>Hong-Tiy, Francis</u> Shipping Services Fiji Ltd. GPO 12671, 2nd Floor, Chauhan E Suva	Managing Director Building, 25 High Street, Toorak	ph fx	(679) 330 5550 (670) 330 1615 fhong-tiy@ssfl.com.fj
Sue, Hing Technic Bitumen Pacific Suva		ph fx	(679) 331 2678 (679) 331 2237
<u>Baleiwai, Jesoni</u> Tropik Woods		ph fx	(679) 666 1388 (679) 666 1561
French Polynesia			
<u>Garrapin,</u> Marine Nationale	Commissaire	ph fx	
Papeete			
Ajonc, Christophe Port Autonome de Papeete BP 9164 Motu Uta Papeete		ph fx	(689) 43 6060 (689) 42 1950
Duchek, Francois	Analyst	ph	(689) 43 6060

Port Autonome de Papeete BP 9164 Motu Uta Papeete		fx	(689) 42 1950 portppt@mail.pf
Vernaudon, Ken Port Autonome de Papeete BP 9164 Motu Uta Papeete	Analyst	ph fx	(689) 43 6060 (689) 42 1950 portppt@mail.pf
Amam, Ollivier Station de Pilotage des Iles de la Se BP9073 Motu Uta Papeete	Pilot ociete 98715	ph fx	(689) 48 0454 (689) 48 0452 pilotmar@mail.pf
Voirin, Francois Station de Pilotage des lles de la Se BP9073 Motu Uta Papeete	Pilot ociete 98715	ph fx	(689) 48 0454 (689) 48 0452 pilotmar@mail.pf
Guam			
<u>Utalan, Jolynn P.</u> Ambyth Shipping and Trading Inc. Apra	Operations Department	ph fx	(671) 477 7250 (671) 472 1254
<u>Gawel, Mike</u> Environmental Protection Agency		ph fx	(671) 472 8863 (671) 477 9402
Apra			
<u>Kaye, Jordan</u> Environmental Protection Agency	General Manager	ph fx	(671) 472 8863 (671) 477 9402
Apra			
<u>Sablan, Richard</u> Marianas Shipping Agencies	General Manager	ph fx	(671) 472 8584 (671) 472 8585
Apra			
Ahillen, Tom Matson Navigation Co.		ph fx	(671) 475 5961 (671) 477 5965
Apra			
Enriquez, Noel Mobil Oil Guam 642 East Marine Drive Agana	Operations Manager	ph fx	(671) 647 9629 (671) 647 9657
O, Linda	Administrative Assistant	ph	(671) 647 9655
Mobil Oil Guam 642 East Marine Drive		fx	(671) 647 9657 linda_o@email.mobil.com
Agana	96910		
Adigum, Abi Mobil Oil Guam/Micronesia/Mariana 642 East Marine Drive Agana	as Islands	<i>ph</i> fx abi	(671) 647 9629 (671) 647 9657 _adigum@email.mobil.com
Santos, Captain Frank G. Port Authority of Guam	Harbourmaster	ph fx	(671) 477 8697 (671) 477 5946
Apra			
<u>Cruz, Joseph R.</u> Seabridge Micronesia, Inc.	General manager	ph fx	(671) 477 0091 (671) 472 1264
Apra			
<u>Labrador, Mar</u> Sealand Services Inc.	General Manager	ph fx	(671) 477 7861 (671) 477 7848
Apra			

Borders, Lieutenant James Safety Branch - U.S. Coast Gurd	Head	ph fx	(671) 339 2001 (671) 339 2005
Apra			
Japan Shiratori, M. Dorval Kaiun K.K. 3rd Floor, Mitamura Bldg., 1-Chome	e Kyobashi Chuo-Ku	ph fx	(81335) 620 801 (81335) 625 233 tokaii@po.dorval.co.jp
Kiiribati			
<u>Riwata, Tabea</u> Kiribati inter-Island Shipping Service	Operations Manager? es	ph fx	(686) 268 39
Betio			
<u>Leuraoi, Captain Koubwere</u> Kiribati Ports Authority	Operations Manager	ph fx	(686) 280 10 (686) 261 64
Betio			
Abee, Teruruai Ministry of Natural Resoources	Assistant Fishing Vessel Registrar	ph fx	(686) 210 95 (686) 211 20
Betio			
Abete, Captain Miteti Marine Department - Ministry of Tra	Director of Marine ansport	ph fx	(686) 260 03 (686) 265 72
Betio			
Mikaere, Tekaai Shipping Agencies of Kiribati PO Box 402 Betio	Manager	ph fx	(686) 264 73 (686) 264 30
<u>Teanako, Baie</u> Te Mautari Ltd.		ph fx	
Betio			
Kiribati			
<u>Tabutoa, Captain R.</u> Kiribati Shipping Serices Ltd.	Operations Manager	ph fx	(686) 261 95 (686) 262 04
Betio			
Etuati, Ms Baraniki Ministry of Environment	Acting Director	ph fx	(686) 285 93 (686) 265 72
Betio			
Marshall Islands			
Hong, Ting (longline fishing fleet)	Owner/Manager	ph fx	(692) 625 5577
Majuro			
<u>Ysawa, Bori</u> Central Pacific Maritime Agency	Shipping Manager	ph fx	(692) 625 3250 (692) 625 3505
Majuro			

Director			Hicking, A. T. Assistant ph(692)
625 3035 Environmental Protection Age	nev	fx	(692) 625 5202
Majuro	ioy	12	(002) 020 0202
PM&O Line	Manager	ph fx	(692) 625 6130 (692) 625 6131
Majuro			
<u>Tiiobeck, Captain Joe</u> Ports Authority	Director	ph fx	(692) 625 8269 (692) 625 4269
Majuro			
New Caledonia			
Lauvray, Joel Port Autonome de la Nouvelle BP 14, 34 av. James Cook Noumea	Caledonia 98845	ph fx	(687) 27 5966 (687) 27 5490 noumeaportnc@canl.nc
Baudchon, Gerald Secretariat General Cooperati BP M2 98849 Noumea	Special Assistant for Regional on Regionale	ph fx	(687) 24 6522 (687) 24 6524
<u>Carre, Hubert</u> Service de la Marine Marchan	Directeur des Affairs Maritime d et des Peches Mariti	ph fx	(687) 28 7286
Noumea			
<u>Duflos, Luc</u> Societe du Pilotage Noumea Bureau du Pilotage, BP 344 Noumea		ph fx	(687) 27 3274 (687) 27 7178 I.duflos@canl.nc
Niue			
Makaola, Luavasu Department of Public Works PO Box 38	Mechanical Superintendent	ph fx	(683) 4297 (683) 4223
Alofi			pwd@mail.gov.nu
			pwd@mail.gov.nu
Alofi	Director and Development	ph fx	pwd@mail.gov.nu (680) 488 8171 (683) 488 1475 BNRD@palaunet.com
Alofi Palau Francisco, Herman Bureau of Natural Resources a PO Box 117		ph	(680)488 8171 (683)488 1475
Palau Francisco, Herman Bureau of Natural Resources a PO Box 117 Koror		ph	(680)488 8171 (683)488 1475
Alofi Palau Francisco, Herman Bureau of Natural Resources a PO Box 117 Koror Papua New Guinea Vagi, Douva		ph fx ph	(680) 488 8171 (683) 488 1475 BNRD@palaunet.com
Alofi Palau Francisco, Herman Bureau of Natural Resources a PO Box 117 Koror Papua New Guinea Vagi, Douva Adsteam Agency (PNG) Ltd.	and Development	ph fx ph	(680) 488 8171 (683) 488 1475 BNRD@palaunet.com
Palau Francisco, Herman Bureau of Natural Resources a PO Box 117 Koror Papua New Guinea Vagi, Douva Adsteam Agency (PNG) Ltd. Port Moresby Rupen, Chris Maritime Division PO Box 1489	and Development	ph fx ph fx	(680) 488 8171 (683) 488 1475 BNRD@palaunet.com
Palau Francisco, Herman Bureau of Natural Resources a PO Box 117 Koror Papua New Guinea Vagi, Douva Adsteam Agency (PNG) Ltd. Port Moresby Rupen, Chris Maritime Division PO Box 1489 Port Moresby Koko, Ilo PNG Harbours Board PO Box 671	and Development t Director ph (675) 321 1866	ph fx ph fx fx	(680) 488 8171 (683) 488 1475 BNRD@palaunet.com (675) 321 2599 (675) 321 1331
Palau Francisco, Herman Bureau of Natural Resources a PO Box 117 Koror Papua New Guinea Vagi, Douva Adsteam Agency (PNG) Ltd. Port Moresby Rupen, Chris Maritime Division PO Box 1489 Port Moresby Koko, Ilo PNG Harbours Board PO Box 671 Port Moresby Jakubovsky, Roman	and Development t Director ph (675) 321 1866	ph fx ph fx fx ph fx	(680) 488 8171 (683) 488 1475 BNRD@palaunet.com (675) 321 2599 (675) 321 1331 (675) 321 1627 (675) 321 1546
Palau Francisco, Herman Bureau of Natural Resources a PO Box 117 Koror Papua New Guinea Vagi, Douva Adsteam Agency (PNG) Ltd. Port Moresby Rupen, Chris First Assistant Maritime Division PO Box 1489 Port Moresby Koko, Ilo PNG Harbours Board PO Box 671 Port Moresby Jakubovsky, Roman Steamships Shipping Agency	and Development t Director ph (675) 321 1866	ph fx ph fx fx ph fx	(680) 488 8171 (683) 488 1475 BNRD@palaunet.com (675) 321 2599 (675) 321 1331 (675) 321 1627 (675) 321 1546

Pitcairn Island Administration P. O. Box 105-696, 67 Customs S Auckland, New Zealand	t.,Shortland	fx ac	(649) 366 0187 dmin@pitcairn.gov.pi
Samoa			
Tominiko, Maselino Ministry of Transport PO Box 1607 Apia		ph fx	(685) 23 70 (685) 21 99
Va'elua, Nofo Ministry of Transport PO Box 1607 Apia	Secretary for Transport	ph fx	(685) 23 70 (685) 21 99
<u>Ulugia, Tommy</u> Morris Hedstrom Samoa Ltd.		ph fx	(685) 22 72 (685) 24 27
Apia			
Schwalger, Steve Pacific Forum Line		ph fx	(685) 20 34 (685) 20 78
Apia			
Tualga, Koki Samoa Shipping Corporation		ph fx	(685 (685
Apia			
<u>Hogarth, Graham</u> Trans/am Samoa Ltd.		ph fx	(685) 21 15 (685) 21 311
Apia			
Singapore			
Olson, Richard ExxonMobil	Chartering Manager	ph fx	(65) 660 641
18 Pioneer Road Singapore			on@email.mobil.coi
Solomon Islands			
Maelaua, Joseph Malaita Shipping Co.		ph fx	(677) 26 20 (677) 23 50
Honiara			
Ahikau, Michael Maritime Division - Miinistry of Tra PO Box G32 Honiara	Superintendent of Marine ansport and Aviation	ph fx	(677) 24 94 (677) 23 79
<u>Ito, Hideyoshi</u> Ministry of Tourism and Transport		ph fx	(677) 21 64 (677) 23 46
Kabui, Ngenomea B. Solomon Islands Port Authority PO Box 307 Honiara	Chief Executive Officer	ph fx	(677) 22 64 (677) 23 99
Constantine, Nick Sullivans Ltd.		ph fx	
Honiara			
Stenzel, Gerald Tradco Shipping Ltd.	Managing Director	ph fx	(677) 22 58 (677) 23 88
Honiara			

$\overline{}$	\sim	ın	
u	ke	ıa	u

I Okciau			
<u>Kirifi, Kirifi</u> Department of Natural Resources a	Director nd Environment	ph fx	(690) 2127 (690) 2108
Tonga			
Cocker, Roger Dateline Shipping Agencies		ph fx	(676) 245 00 (676) 239 33
Nuku'alofa			
<u>Faupula, Sepuloni</u> Forum Shipping Agencies		ph fx	(676) 23 012 (676) 23 345
Nuku'alofa			
Latu, Hua JFM Shipping Agency		ph fx	(676) 23 334 (676) 24 070
Nuku'alofa			
<u>Faka'osifolau, Ma'ake</u> Mark Shipping Ltd.		ph fx	(676) 22 699 (676) 24 099
Nuku'alofa			
Fuapau, L.			Assistant Marine Officer ph (676) 70 639
Ministry of Marine and Ports GPO Neiafu Neiafu		fx	(0.0) 10 000
<u>Vikilani, S.</u> Ministry of Marine and Ports PO Box 144 Nuku'alofa	Acting Secretary for Marine and Ports	ph fx	(676) 22 555 (676) 26 234 marine@kalianet.to
<u>Tu'inukuafe, Ms. Amelia</u> Pacific Shipping Agencies		ph fx	(676) 23 311 (676) 23 195
Nuku'alofa			
Tufui, A. SCP Agency		ph fx	(676) 21 699 (676) 22 617
Nuku'alofa			
Tuvalu			
Sinapati, Uale Marine and Ports Services Private Mail Bag Funafuti	Acting Director	ph fx	(688) 20 052 (688) 20 722 marine@tuvalu.tv
<u>Luaseve, Seve</u> Ministry of Works, Communications Private Mail Bag Funafuti	Secretary and Transport	ph fx	(688) 20 052 (688) 20 722
Vanuatu			
Roosen, John T. Vanuatu Maritime Authority PO Box 320, Maritime Resource Ce Port Vila	Chief Executive Officer	ph fx	(678) 23 768 (678) 22 949 vma@vanuatu.com.vu
Yvon, Firiam Vanuatu Maritime Authority PO Box 320 Port Vila		ph fx	(678) 23 128 (678) 22 949 vma@vanuatu.com.vu

Wallis and Futuna

Lauvray, Joel Port Autonome de la Nouvelle Caledonia BP 14, 34 av. James Cook	1	<i>ph</i> fx no	(687) 27 5966 (687) 27 5490 umeaportnc@canl.nc
Noumea	98845		
Service des Duanes et Affairs Maritimes Aka'aka - District de Hahake BP 06		ph fx	(681) 72 2571 (681) 72 2986
Mata-Utu	98600		
Vanai, Paino Che Service Territorial de l'environnemen BP 294	ef du Service del'environnement	ph fx	(681) 720 351 (670) senv@wallis.co.nc
Mata-Utu	98600		

2 APPENDIX 2: DATABASE STRUCTURE: ACCESS DATABASES AND MAPINFO GIS

The organizing principle for analysis was that Microsoft Access would be used as far as practical for primary data storage and statistical analysis, with MapInfo GIS for thematic presentations and geospatial analyses of risk potential.

VesselTraffic.mdb WorldPositionsP.mdb Vessels.mdb Contains detailed traffic data on regional Worldwide list of ports Names of vessels and shipping, keyed to routes by begin and end and port lat/long classes of vessels, with ports and coded for analysis by frequency, Access database MarRisks locations . All added details of size, type, volume, and ver †tvne. ports and waypoints owner/line, flag will be appended to this AssembleSubRouteData database. Added fields permit coding by port This query calls a series of crosstabs queries that or waypoint assemble Vessel Traffic data for each route, and significance (world. summarise as frequencies and tonnage for each regional, local) and vessel type on each route. Then this system study country. Table is breaks each route into subroutes, sums data for nranarad & naihona each subroute, and assigns geographic coordinates to each subroute node. В WorldP.tab . a low SubRouteStats.tab PacPositionsP.tab PacEEZ.tab resolution world vector MapInfo query selects MapInfo is directed to open Map of PICT shoreline map provided by MapInfo workspace PacRoutes.wor SubRouteStats.xls and store the data ports and waypoints EEZ's MapInfo. is the common background for small scale as a Mapinfo table. Custom Mapinfo of interest. Data flow provided by presentations. At larger is both ways, so that utility createline.mbx. is then run, SOPAC, with scales, this is replaced by additions, deletions or producing a geocoded line segment one higher resolution layers for each subroute. Thematic mapping corrections to additional Asauspol.tab and is applied to represent vessel field to code aeocoded positions Reefs.tab provided by frequency and tonnage per year as and associated data in for SOPAC. lines of width proportional to traffic either table will be membershin These four layers form the basic thematic mapping tool for this study. They are also the primary basis for analyzing grounding and collision risks at the regional, country and port levels.

Casualties.mdb

Database of PICT region marine incidents, prepared for MapInfo geocoding in Pacific-centered convention. Casualties contains information from previous "Ship Groundings ..." SPREP report up larged by

NQ2000.txt

FishActiv.mdb

Casualties.tab

MapInfo thematic map showing casualty locations, by type and severity. Info Tool permits interactive reference to Casualties database text details.

NQ2000ByVesselType.

Allows us to compare the actual position sequences of large commercial vessels with the routes inferred from interviews and sailing directions.

FishActiv.tab

MapInfo thematic map showing longline and purse seine tuna fishing activity..

EnvSensP.tab

Placenames and locations associated with discussions of environmental sensitivity, ballast/deballast operations, etc.Locations digitised

Auxiliary databases and map layers

3 APPENDIX 3: VESSELS, POSITIONS AND TRAFFIC

The Microsoft Access database MarRisk2.mdb contains all of the raw data on vessels, vessel traffic, positions and routes. The primary tables are quite large – about 1911 vessel traffic records for 656 vessels over 5017 route segments between 918 positions. Here we present the database table structures as an introduction to the electronic databases, which are provided on compact disk. Printed records can be obtained by running the report utilities PrintVessels, PrintVesselTraffic PrintPacPositionsP and PrintRoutesSubRoutes provided in MarRisk2.mdb:.

The "2" in MarRisk2.mdb refers to the fact that it is an Access 2002 database.MarRisk.mdb is the same data and functionality in an Access 97 database.

Structure of Microsoft Access database MarRisk2.mdb

Table: ISO3166CountryCodes

Properties

ISO 3166 is the list of official country names, two-character country codes and 3-character codes.

Columns

Name	Туре	Size
ID	Long Integer	4
Country	Text	50
ISO2	Text	5
ISO3	Text	5
ISONumber	Text	5

Table: PositionTypes

Properties

Codes to distinguish position types, for example P1 for major world ports, W1 for ocean waypoints.

Columns

Name	Type	Size
ID	Long Integer	4
Position_Type	Text	2
Comment	Memo	

Table: MAPINFO_MAPCATALOG

Properties

MapInfo internal bookkeeping

Columns

Name	Type	Size
SPATIALTYPE	Double	8
TABLENAME	Text	32
OWNERNAME	Text	32

SPATIALCOLUMN	Text	32
DB_X_LL	Double	8
DB_Y_LL	Double	8
DB_X_UR	Double	8
DB_Y_UR	Double	8
OOODDINATEO/		- .
COORDINATESYS	SIEM	Text
254	SIEM	Text
	Text	254
254		
254 SYMBOL	Text	254

Table: PositionTypes

Properties

List of standard codes to distinguish positions by type, for example P1 for major world port, W for waypoint.

Name	Туре	Size
ID	Long Integer	4
Position_Type	Text	2
Comment	Memo	-

Table: RoutesSubRoutes

Properties

Table of the subroutes that form the line segments of each route from port to port. All Routes and Subroutes are named by their begin and end position codes from WorldPositionsP.

Columns

Name	Type	Size
MAPINFO_ID	Long Integer	4
RouteName	Text	11
PACPOLArea	Text	1
SubRouteBegin	Text	5

SubRouteEnd	Text	5
OrderInRoute	Integer	2
SubRouteName	Text	10

Table: Vessels

Properties

Vessel names, tonnages, flags and other characteristics.

Name	Type	Size
VessellD	Long Integer	4
Line	Text	30
VesselOrClass	Text	30
VesselType	Text	5
Flag	Text	5
GRT	Long Integer	4
LOA	Integer	2
TEU	Integer	2
DWT	Long Integer	4
YearBuilt	Integer	2
SpeedKn	Single	4
Passengers	Integer	2
Crew	Integer	2
VesselComment	Memo	-

Table: VesselTraffic

Properties

The main table of detailed data on traffic from port to port by vessel and voyages/year.

Columns

Name	Type	Size
VeTrID	Long Integer	4
VesselOrClass	Text	30
RouteBegin	Text	5
RouteEnd	Text	5
Variant	Text	1
RouteName	Text	11
Frequency	Single	4
Comment	Memo	-
DataYear	Text	5
DataCollBy	Text	3
DataEntryBy	Text	3
LastEditBy	Text	3
LastEditDate	Date/Time	8

Columns

Name	Туре	Size
VeTyID	Long Integer	4
ListOrder	Integer	2
VesselType	Text	5
VesselTypeDef	Text	50
DefaultGRT	Long Integer	4
DefaultDWT	Long Integer	4
DefaultTEU	Integer	2
DefaultPopulation	Integer	2
Comment	Memo	-

Table: WorldPositionsP

Properties

A large list of world ports, plus ports and waypoints added for this study, coded for position type, and including coordinates in Lat/Long by decimal minutes (traditional) and decimal degrees (for MapInfo)XCOORDP contains decimal degree longi in Pacific-centered format (0-360 degrees eastward)

Columns

Name	Туре	Size
MAPINFO_ID	Long Integer	4
Position	Text	50
P_Code	Text	5
Country	Text	50
C_Code	Text	5
Position_Type	Text	5
PacIsland	Text	5
Latitude	Text	10
Longitude	Text	11
XCOORD	Single	4
YCOORD	Single	4
XCOORDP	Single	4

Table: VesselTypes
Properties

4 APPENDIX 4: CASUALTIES

Provisional database of ship casualties with significant potential to cause marine pollution. January 1976 – October 2000, in 22 Pacific Island countries and territories

Key to abbreviations

Vessel Type

<u>vesser rype</u>				
		<u>Incide</u>	ent type	
Toil	Tanker (crude oil and petroleum			
produc	ets)	G	Grounding (details unknown)_	
Tchem	n Tanker (chemicals)	GP	Grounding under power	
Tlpg	Tanker (LPG)	GD	Grounding adrift	
Ctr	Container vessel	С	Collision	
RoRo	Roll-on roll-off cargo vessel	F	Fire	
CG	Mixed cargo (break bulk)	M	Mechanical	
Bulk	Bulk cargo	Н	Hull	
OBO	Oil-bulk-ore	S	Storm	
R	Reefer	0	Other	
FC	Ferry (Cargo and passenger)	U	Unknown	
FP	Ferry (primarily passenger)			
SP	Specialized function	Seve	rity of incident	
FV	Fishing Vessel			
LC	Landing Craft	Т	Total loss	
Other	Other	Р	Partial loss	
CL	Cruise Liner	M	Minor Damage	
U	Unknown_	U	Unknown	
	-			

Structure of database CasualtyReports2.mdb

<u>Table: Casualties</u> Properties

The table of casualties with significant pollution potential in the Pacific Islands Region, 1976-2002 – coded by type and severity, and georeferenced.

Columns

Name	Type	Size
ID	Long Integ	ger 4
VesselName	Text	50
Flag	Text	20
Type	Text	20
GRT	Long Integ	ger 4
YearBuilt	Integer	2
DateIncident	Date/Time	8
CountryOfIncident	Text	50
LocationName	Text	50
Latitude	Text	10
Longitude	Text	11
TypeIncident	Text	5
Severity	Text	5
Comments	Text	255
YCOORD	Single	4
XCOORD	Single	4
XCOORDP	Single	4
CoordChangeFlag	Yes/No	1

Table: IncidentTypeCodes

Properties

Columns

Name	Туре	Size
ID	Long Int	eger 4
IncidentTypeCode	Text	50
IncidentType	Text	50

Table: ISO3166CountryCodes

Properties

Columns

Name	Туре	Size
ID	Long	Integer 4
Country	Text	50
ISO2	Text	5
ISO3	Text	5
ISONumb	er Text	5

Table: MAPINFO MAPCATALOG Properties

MapInfo internal bookkeeping

Columns

Name	Type	Size
SPATIALTYPE	Double	8
TABLENAME	Text	32
OWNERNAME	Text	32
SPATIALCOLUMN	Text	32
DB_X_LL	Double	8
DB_Y_LL	Double	8
DB_X_UR	Double	8
DB_Y_UR	Double	8
COORDINATESYS1	ΓΕΜ Text	254
SYMBOL	Text	254
XCOLUMNNAME	Text	32
YCOLUMNNAME	Text	32

Table: VesselTypes

Properties

Standard vessel type categories, with default tonnage values.

Columns

Name	Type :	Size
VeTyID	Long Intege	r 4
ListOrder	Integer	2
VesselType	Text	5
VesselTypeDef	Text	50
DefaultGRT	Long Intege	r 4
DefaultDWT	Long Intege	r 4
DefaultTEU	Integer	2
DefaultPopulation	Integer	2
Comment	Memo	-

Detailed contents of table Casualties

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Hoto Maru - -	JP	U U	60 T	1978	Sank. All crew rescued.
Celtic Kiwi - -	NZ 27-Oct-1991	U O	0 T	0	Sank after leaving NZ. 13 crew members rescued by 'Rock Steady' and brought to NZ. Was carrying 850 tonnes of cement.
Michelangelo American Samoa Reef Outside Tafun	- 22-Dec-1978 a Airport, Tutuila	FV GP 14°21.00'S	1066 T	1970 170°49.00'W	Stranded, refloated & proceeded to Whangarei for repairs. Vessel sank whilst proceeding to Whangarei.
Hsiung Hsing American Samoa Off Tutuila Island	- 09-Jun-1980	FV GP 14°17.00'S	187 T	1977 170°39.00'W	Wrecked. During salvage operations ship capsized
Jui Man No.3 American Samoa Off Pago Pago	- 08-Apr-1981	FV GP 14°16.70'S	216 P	1969 170°35.20'W	Wrecked in heavy weather. Cargo fish. Extensive damage to double bottom allowed small quantity of fuel to leak out. Failry extensive damage. Fire after grounding.
Kwang Myung No. 65 American Samoa Pago Pago, Samor	31-Oct-1982	FV GP 14°18.00'S	352 T	1968 170°38.00'W	Stranded, refloated, taken to inner port where sank, remaining partly submerged. Oil and fuel removed from vessel. 12 tonnes of oil collected from beach and disposed of.
Vessel Name Country of	Flag Date of Incident	Type Type	GRT Sever	Year Built ity	Comments

Incident Location Name		Incident Latitude		Longitude	
Young Kwang No.1 American Samoa	- 22-Jun-1985	FV GP	233 T	1963	Wrecked in heavy weather. Vessel holed and engine room flooded
Aunun (Aunuu?) Isla	nd	14°17.00'S	3	170°33.00'W	
Fotu o Samoa American Samoa	- 22-Mar-1991	LC GP	271 P	1979	Stranded, refloated, taken to Pago Pago for survey and repair. Bottom buckled and distorted. Damage to a tank
Reef at Fa'asouga P	oint, Tau Island	14°17.00'S	5	169°31.00'W	and rudder.
Koram No.3 American Samoa	- 08-Dec-1991	FV GD	304 T	1973	Wrecked on reef during Cyclone Val (6-10 Dec 1991). Removed from reef and sunk in deep water on 16 Mar
Pagopago Harbour		14°17.00'S	3	170°40.00'W	2000.
Koram No.1 American Samoa	- 08-Dec-1991	FV GD	304 T	1973	Wrecked on reef during Cyclone Val (6-10 Dec 1991). Later cut down to water line and scrap metal dumped at
Pagopago Harbour		14°17.00'S	3	170°40.00'W	sea.
Kwang Myung No.63 American Samoa	- 08-Dec-1991	FV GD	352 T	1968	Wrecked on reef during Cyclone Val (6-10 Dec 1991). Later cut down to water line and scrap metal dumped at
Pago Pago Harbour	□ a	14°17.00'S		170°40.00'W	sea.
Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
					
Kwang Myung No.51 American Samoa	- 08-Dec-1991	FV GD	347 T	1967	Wrecked on reef during Cyclone Val (6-10 Dec 1991).
Pago Pago Harbour	00-060-1991	14°17.00'S	-	170°40.00'W	Later cut down to water line and scrap metal dumped at sea.
Miga No.5	-	FV	0	0	Wrecked on reef during Cyclone Val (6-10 Dec 1991).

American Samoa Pagopago Harbour	08-Dec-1991	GD 14°17.00'S	T S	170°40.00'W	Later cut down to water line and scrap metal dumped at sea.
Yute No.1 American Samoa Pagopago Harbour	- 08-Dec-1991	FV GD 14°17.00'S	0 T	0 170°40.00'W	Wrecked on reef during Cyclone Val (6-10 Dec 1991). Removed from reef and sunk in deep water 19 Mar2000.
Korbee No.7 American Samoa Pago Pago Harbour	- 08-Dec-1991	FV GD 14°17.00'S	304 T	1974 170°40.00'W	Wrecked on reef during Cyclone Val (6-10 Dec 1991). Later cut down to water line and scrap metal dumped at sea.
Kwang Myung No.72 American Samoa Pagopago Harbour	- 08-Dec-1991	FV GD 14°17.00'S	346 T	1969 170°40.00'W	Wrecked on reef during Cyclone Val (6-10 Dec 1991). Later cut down to water line and scrap metal dumped at sea.
Kwang Myung No.58 American Samoa Pagopago Harbour	- 08-Dec-1991	FV GD 14°17.00'S	347 T	1968 170°40.00'W	Wrecked on reef during Cyclone Val (6-10 Dec 1991). Later cut down to water line and scrap metal dumped at sea.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Amiga No.5 American Samoa Pago Pago	- 10-Dec-1991	FV GP 14°17.00'S	284 T	1970 170°40.00'W	Stranded during Cyclone Val
Kao Ya No.137 American Samoa Pagopago Harbour	TA 13-Nov-1996	FV C 14°21.00'S	560 P	1990 170°40.00'W	Collided with BHP fuel dock causing a spill of 600 gallons of oil into harbour.
Adriatic Sea American Samoa 90 miles north of Tu	US 23-Jan-1998 utuila	FV S 12°40.00'S	1559 T	1970 170°50.00'W	Sank in rough seas. Crew safely rescued.
Capt. Cristiano da Ro American Samoa One mile off Americ	04-Oct-1998	FV M 13°35.00'S	1348 M	1986 169°42.00'W	Reported taking on water. Safely towed to Pagopago
Laura Australia Near Wessel Island	FR 26-Feb-1998	CG M 10°50.00'S	0 T S	0 137°30.00'E	Sunk. Developed engine problems in rough seas and developed a heavy list. Crew abandoned vessel and were later rescued. Vessel was being towed when it sank.
Teknik Putra Australia Thursday Island	PA 24-Jan-2000	Other GP 10°34.28'S	1009 M	1980 142°14.90'E	Vessel grounded lightly. Refloated with tug assistance. Minor damage to propellor, none to hull.
Pratidina 05 Australia Numar Reef, Torres	ID 13-Nov-2000 s Strait	FV U	0 T	0	Vessel grounded. Ten crew removed and returned to Indonesia. Vessel not found by subsequent aircraft patrols, presumed sunk.
Doric Chariot	GR	Bulk	0	0 A4-11	Vessel ran aground northbound after failing to execute a

Australia Piper's Reef, 330 nm	29-Jul-2002 ni N Cairns	GP 12°15.00'S	P ;	143°14.00'E	planned turn. Cargo coal. Extreme damage to Breat Barrier Reef feared, but vessel was refloated with tug assistance on 08 Aug 02. No oil or cargo lost. TBT antifoulant and mechanical damage to reef.
Aremiti Australia?	PF 17-Aug-1996	FC H	608 M	1994	Enroute Singapore to Fiji. Entered Stephens Islet due to taking water. Proceeded to Cairns for repairs.
Stephens Islet		09°30.00'S	;	143°33.00'E	
Shotoku Maru No.65 Cook Islands	- 24-Aug-1978	FV GP	339 P	1962	Stranded, refloated and towed to Suva. Condemned.
Nassau Island	J	11°33.00'S	}	165°25.00'W	
<u>Lien Ho No.1</u> Cook Islands	- 02-Mar-1981	FV GP	162 T	0	Wrecked in heavy weather. Crew rescued from Pukapuka Island.
Reef off Pukapuka Is	sland	10°55.00'S	;	165°51.00'W	
<u>Manuvai</u> Cook Islands	- 28-Dec-1988	CG GP	284 T	1960	Stranded. Holed during refloating attempts.
Reef at Nassau Islar	nd	12°00.00'S	,	168°00.00'W	

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Edna Cook Islands	- 28-Nov-1990	CG GD	132 P	1918	Stranded after dragging anchors in heavy weather
Atui (Atiu) Island		20°02.00'\$	>	158°07.00'W	
<u>Fiammetta</u> Cook Islands	GB 13-Aug-1991	U GD	9 T	1957	Dragged anchor, drifted onto rocks and sank.
Avarua Harbour	3	21°12.00'	S	159°47.00'W	
<u>Marthalina</u> Cook Islands	NZ 21-Feb-1992	U GP	0 M	0	Ran aground. Later floated off with no damage.
Penrhyn Island		09°00.00'	3	158°00.00'W	
Acadea B Cook Islands	US 16-Mar-1992	FV S	M	1977	Damaged while berthed at Rarotonga during Cyclone 'Gene'. Vessel had disabled engine.
Rarotonga		21°12.00'\$	3	159°47.00'W	<u> </u>
Acadea B Cook Islands	CK 02-Sep-1995	CG O	69 T	0	Sank enroute to Northern Islands. Overloading of cargo possible cause
-	02 0 0p 1000	16°56.00'S	•	159°10.00'W	possisio saass
<u>Kaunitoni</u> Cook Islands	FJ 02-Sep-1995	FP M	384 M	1975	Disabled (engine breakdown) and adrift at sea on way from Rarotonga to Mururoa Atoll to take part in protest against
	east of Rarotonga	21°13.54'		154°18.34'W	resumption of nuclear testing. Towed to Rarotonga for repairs.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Orongo - Cook Islands Reef at Aitutaki, n	Tug 0 0 04-Jan-1996 orth of passage	Tug and C 18°50.00'S	P	went aground in he	avy rain and poor visibility. Subsequently salvaged.
Kura Ora Cook Islands Two miles off Puk	PF 30-Sep-1996 apuka	U H 10°40.00'S	299 T	1967 165°35.00'W	Foundered after ingress of water in hold through crack in shell plating.
Avatapu Cook Islands -	NZ 21-Feb-1997	FC O 20°30.00'5	0 T	0 160°30.00'W	Abandoned by passengers/crew. Vessel since not sighted and presumed to have sunk
Aroa Nui Cook Islands Reef at Atiu	CK 15-Jun-1998	CG GP 19°59.00'S	117 T	1968 158°08.00'W	Stranded. Engine room holed and flooded. Expected to be constructive total loss.
Thor Lisbeth Cook Islands?	06-Nov-1995	Ctr GP 19°31.40'5	1395 M	0 159°43.72'W	Ran aground on a reef. Able to free herself. Proceeded to Rarotonga
<u>Ika Vuka</u> Fiji Reef off Toberua	- 27-Feb-1977 Island	CG GP 17°58.00'S	180 T	1944 178°45.00'E	Stranded, refloated and taken to Savusavu Bay. Condemned. Cargo copra.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
<u>Ji Nam No.22</u> Fiji	- 16-Feb-1978	FV GP	194 P	1965	Grounded, refloated and towed to Suva for repairs.
Southern Reef		18°30.00'S	5	177°55.00'E	
<u>Nam Hai No.231</u> Fiji	- 14-Mar-1978	FV GP	159 T	1965	Grounded in heavy rain on dark night. Subsequently capsized in heavy seas during 2nd salvage attempt. Crew
Off Suva Harbour o	on reef	18°10.00'S	3	178°25.00'E	taken off and vessel abandoned. Cause unknown currents. Attempts to salvage remaining cargo (bulk fertiliser)
<u>Mobil Producer</u> Fiji	- 09-Jun-1978	Toil GP	18258 M	-	Stranded on soft mud patch. Refloated without any assistance, examined and proceeded. Minimal
North of Viti Levu		17°12.90'S	5	177°33.40'E	damage.Sailed for Singapore.
<u>Akhilles</u> Fiji	- 15-Nov-1978	FV GP	2654 M	1970	Grounded, refloated with assistance of sister ships and continued on voyage.
On Reef Suva Harb	oour	18°10.00'S	3	178°24.00'E	
<u>Cenpac Rounder</u> Fiji	- 28-Mar-1979	FP GP	3179 T	1961	Stranded in heavy weather (winds from passing cyclone). Refloated, towed to Suva and thence taken to Busan and
Votualailai Reef, Of	ff Suva	18°30.00'S	3	177°40.00'E	broken up.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
<u>Colville</u> Fiji	- 18-Apr-1979	CG GP	123 T	1943	Stranded and sank. Raised, repaired and refitted.
Reef off Tavua	•	17°20.00'5	3	177°53.00'E	
<u>Tui Cakau II</u> Fiji	- 26-Jul-1979	RoRo GP	1965 M	1961	Stranded, refloated without assistance and continued on voyage. Some bottom damage.
Off Lautoka		17°31.00'5	3	177°24.00'E	
Kwang Myung No.9 Fiji	- 22-Mar-1980	FV GP	236 P	1966	Stranded, refloated and taken to Suva for repairs. Prior to refloating fish and bait were removed by helicopter.
Cakaulekaleka Ree	f, SW of Vatulele	18°28.00'\$	6	177°37.00'E	Moderate damages to 80% of bottom extending to P&S bilge keels. No damage to stern gear and skeg.
<u>Pacific Gas</u> Fiji	- 08-Nov-1980	TIng GP	903 P	1967	Stranded, refloated without assistance and proceeded to Suva for discharge. Shell plating set up in isolated places.
1 mile north of Navu	ıla Light	17°53.00'S	3	177°12.00'E	
Nam Pyung No.5 Fiji	- 24-Nov-1980	FV GP	218 M	1962	Stranded, refloated with tug assistance and proceeded for inspection. No repair was necessary, returned to service.
Reef In Suva Harbo	ur	18°10.00'S	3	178°24.00'E	

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ty	Comments
Location Name		Latitude		Longitude	
<u>Tokerau</u> Fiji	- 24-Dec-1980	CG GP	349 T	1937	Stranded, refloated with assistance and towed to Suva where brokem up. Entire bottom hull corrugated, keel
Reef 37 km NNW o	of Yandua Island	16°28.00'S	5	178°12.00'E	strake set up and buckled, 3 propeller blades bent, main engine and auxiliary engine water damaged.
<u>Stardust II</u> Fiji	- 15-Jan-1981	FP GP	159 P	1945	Stranded after 73-knot winds. Returned to service. Needed port propellor shaft and minor repairs to the timber hull.
Suva Harbour (also Nadi")		18°10.00'S		178°24.00'E	port propellor shart and millior repairs to the timber hull.
<u>Taoniu</u> Fiji	- 15-Jan-1981	CG GD	514 M	1958	Stranded during Cyclone Arthur. Refloated with no serious damage.
In Suva Harbour		18°10.00'S	3	178°25.00'E	
<u>Dae Yang No.10</u> Fiji	- 30-Dec-1981	FV GP	192 T	1964	Stranded during Cylcone Eric. Refloated and taken to Suva. Scuttled. At least one double bottom fuel tank
Off Suva Harbour		18°10.00'S	3	178°25.00'E	breached and oil leaked to sea.
<u>Viti</u> Fiji	- 27-Aug-1982	FP GP	114 T	1941	Struck reef and sank approx. 5 miles off Lautoka. All crew members and passengers rescued.
Tivoa Reef		17°37.10'S	3	177°21.50'E	

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
<u>Kekanui</u> Fiji	- 02-Mar-1983	CG GD	400 M	1954	Stranded after dragged anchor during Cyclone Oscar (1-2 Mar 1983). Refloated by own means and towed back to
Suva Harbour		18°08.00'S	3	178°25.00'E	anchorage by Ports Authority tug where re-anchored.
<u>Fiji Gas</u> Fiji	- 22-Oct-1983	Tlng GP	1587 M	1972	Stranded, refloated without assistance. No major bottom damage, continued on voyage to Labasa.
Reef north of Lauto	ka	17°29.00'S	3	177°26.00'E	
<u>Pacific Shell</u> Fiji	- 15-Jan-1984	Toil GP	493 M	1975	Touched bottom in river, continued on voyage, surveyed at Suva, where repairs effected. Minor repairs.
Labasa River		16°24.00'S	3	179°20.00'E	
<u>lka No.5</u> Fiji	- 27-Apr-1984	FV GP	105 P	1980	Ran aground on reef. All passengers and crew rescued, no injuries. Vessel's hull extensively damaged, oil tanks
Cakaulevu Reef, La	au	18°52.00'\$	8	178°22.00'W	leaking. Refloated, towed to Suva, repaired and returned to service.
<u>Independence</u> Fiji	- 07-May-1984	FV GP	125 P	1983	Stranded, refloated with assistance and towed to Suva. Later repaired and returned to service. Crew rescued. Hull
Vatu Vula Reef, nea	ar Makogai Island	17°28.00'S	3	178°55.00'E	holed.

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
Na Mataisau Fiji Reef off Moala Isla	- 17-Jan-1985 ind	FC GD 18°44.00'S	274 T	1978 179°50.00'E	Sustained main engine breakdown 6 miles SW of Moala Island, struck reef and sank off Moala after draggging anchor during Cylone Eric. 2 died. Mast and other gear removed and recovered and vesseal left as lies in 15-18 meters of water.
<u>Kekanui</u> Fiji Northern Anchorag	- 18-Jan-1985 ge, Suva Harbour	CG GD 18°07.00'S	400 T	1954 178°25.00'E	Stranded whilst anchored in Suva during Cyclone Nigel. Sank in Northern Anchorage in heavy weather. Vessel was looted by local fishermen.
Matthew Flinders Fiji Reef in Saweni Ba	- 05-Mar-1985 y	FP GP 17°37.00'S	1002 P	1954 177°25.00'E	Dragged anchor and stranded on reef during Cyclone Gavin. Refloated and proceeded to Lautoka. Refloating hampered by heavy winds and rough seas, tug assisted. Some bottom and propeller damage.
Young Kwang No.1 Fiji Suva Harbour	- 13-Apr-1985	FV GP 18°10.00'S	233 P	1963 178°24.00'E	Stranded whilst departing Suva in heavy weather, refloated without assistance and anchored. Returned to service. Port bilge keel buckled.
Pacific Shell Fiji Coral reef betweer Lautoka	- 04-May-1985 n Labasa and	Toil GP 16°25.00'S	493 M	1975 178°17.00'E	Stranded whilst on voyage from Labasa to Lautoka. Refloated without assistance and proceeded on voyage. Minor damage.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
<u>lka No.1</u> Fiji	- 11-Feb-1986	FV GP	114 P	1972	Stranded whilst manoueuvering through channel. Refloated and returned to Lautoka. Subsequently flooded,
Mana Island channe	el	17°40.00'S	5	177°07.00'E	towed and beached. Part of vessel badly damaged.
<u>Talofa</u> Fiji	- 15-Apr-1986	LC GD	141 P	1984	Capsized and stranded after sustaining steering trouble. Refloated and towed to Suva for repairs. 8 crew members
Reef at Yasawa Isla	•	16°42.00'S	8	177°35.00'E	missing.
<u>Kaunitoni</u> Fiji	- 08-Aug-1986	FP GP	384 P	1975	Stranded in good weather, refloated and taken to Suva for repairs. All passengers and crew safely rescued. Hull
Mabulithi Reef, sou	th of Gau Island	18°13.00'S	3	179°18.00'E	bottom holed.
<u>Boral Gas</u> Fiji	- 19-Apr-1987	TIng GP	1897 M	1970	Stranded, refloated without aid. Slightly damaged.
Entrance to Navula Bay, Nadi	•	17°55.06'S		177°13.00'E	
<u>Shin Chyun No.7</u> Fiji	- 22-Jun-1988	FV GP	163 P	1974	Stranded, refloated and towed to Suva for repairs. Sold, renamed 'Tasu No.2'. Engine room flooded.
300 miles SW of Fij	i	21°40.00'S	3	174°32.00'E	

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
<u>Matthew Flinders</u> Fiji Navatu Reef, SE of	- 11-Jul-1989 Moala Island	FP GP 18°39.00'S	1002 T	1954 179°33.00'W	Wrecked. Passengers and crew rescued. Hold and engine room flooded.
Mollie Dean Fiji 8 miles SE of Bega	FJ 13-Aug-1991	U H 18°32.00'S	110 T	0 178°17.00'E	Sank. Passengers rescued by Fiji Navy vessel. Salvage not possible.
Polynesian Link Fiji Port of Suva	- 15-Oct-1991	Ctr O 18°08.00'S	0 T	0 178°25.00'E	Sank in Suva Harbour alongside the Kings Wharf obstructing part of wharf. Floating containers of meat were looted. Vessel a constructive total loss. Subsequently wreck was removed and scuttled in deep water outside Suva Harbour.
<u>Wairua</u> Naikorokoro Fiji Near Namalata Ree	- 08-Aug-1993 efs	FP GP 18°58.00'S	618 T	1961 178°08.00'E	Wrecked, 13 miles NE of Cape Washington, off
Arauco Fiji Reef off Labasa	- 15-Feb-1994	Bulk GP 16°34.00'S	15080 P	1979 179°23.00'E	Stranded, refloated with tug assistance and taken to Savusavu for temporary repairs. Taken to Singapore for repairs. Sustained damage to forepeak double bottom tank and water in one hold.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Congresso del Partic Fiji	<u>lo</u> CU 09-Jun-1994	Bulk M	9626 P	1975	Broke down and drifted without power en route for Noumea. Vessel located and towed to Fiji. Some
-		19°47.71'S	3	176°00.44'E	damages. Cargo bagged fishmeal.
<u>Kin Sin II</u> Fiji	- 10-Jul-1994	FV F	0 T	0	Taiwanese trawler reported burning as a result of an internal explosion. Crewmen rescued by NZ Air Force.
90 km south of Nac	di	18°37.00'S		177°22.00'E	
<u>Rybnovsk</u> Fiji	MA 06-Oct-1994	Ctr O	0 M	0	Listed 45 degrees during unloading. Two dock workers injured. Water pumped from engine room to stablize
Suva		18°08.00'S	3	178°25.00'E	vessel.
<u>Garden Sun</u> Fiji	- 13-Jan-1995	FV GP	100 M	0	Grounded due to poor navigation. Refloated without assistance on high tide.
Nanuku Reef		16°40.00'S	3	179°26.00'W	
<u>Archer</u> Fiji	- 03-Feb-1996	FV F	0 T	0	Caught fire at wharf. Towed into harbour by vessel 'Playing Hookey' and navy vessel 'Maika Tora'. After fire
Waters within Suva	Harbour	18°08.00'S	3	178°25.00'E	out, towed r back to Kings Wharf. Vessel later the centre of dispute, unlawfully removed and stripped of equipment.

<u>Vessel Name</u> Country of	Flag Date of Incident	Type Type	GRT Sever	Year Built rity	Comments
Incident		Incident			
Location Name		Latitude		Longitude	
	Other 0 0			cued by Fiji Navy. L	Lower portion flooded.
Fiji	27-Dec-1996	GP	Р		Salvage operation by Marine Pacific Ltd.
-				000°00.00'E	
Dong Huai	-	FV	0	0	Oil spill from sinking vessel. Firefighters used spill
Fiji	30-Jan-1997	Ο	T		dispersant to lessen pollution risk. Vessel abandoned
Near naval base, W	/alu Bay	18°07.00'S	3	178°25.00'E	about a year before the incident.
D 1 NI 0			•		T 0 1
Bulou Ni Ceva	FJ	FP	0	0	Towed to Suva Harbour. Sustained minor damage. Back to
Fiji	07-May-1997	M	M	470000 0015	regular schedule.
-		18°15.00'S	o ·	178°26.00'E	
Arctic P.	ВА	Other	0	1970	Serious bottom damage sustained after went aground.
Fiji	25-May-1997	GP	Р		Yacht.
-					
<u>Jubilee</u>	JP	RoRo	0	0	Grounded, flooded and sank.
Fiji	18-Jul-1998	GP	Ť	•	
Reef off Nabuwalu					
<u>Sofe</u>	FJ	RoRo	997	1968	Developed heavy list in rough seas. Damaged vehicles on
Fiji	22-Jul-1998	S	М		board.
Near Naselai Passa	age	18°12.00'S	3	178°35.00'E	

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi		Comments
Location Name		Latitude		Longitude	
<u>Ulu 1</u> Fiji	FJ 27-Aug-1998	FV U	0 T	0	Sank.
Udu Point, Northern Levu		16°00.00'\$	3	179°54.00'W	
Fortuna No.8 Fiji Near Mavutulevu V	- 21-Sep-1999 'illage, Viti Levu	U GP	0 P	0	Ran aground. Initial efforts to refloat vessel failed. Authorities working to refloat the vessel. No casualties reported.
<u>Kamoea</u> Fiji	TO 21-Dec-1999	U U	0 T	0	Capsized. Navy sent a search for the vessel and five missing seamen the following day.
Lau Waters		19°16.00'S	3	179°17.00'W	
<u>Pacific Mariner</u> Fiji	FJ 27-Feb-2000	Toil G	1384 M	1977	Tanker grounded near Shell Oil terminal, Taveuni. Area to be resurveyed indicates possible uncharted obstacle.
Waiyevo, Taveuni		16°52.50'S	3	159°57.00'E	
<u>Charng Yih No.12</u> Fiji	TA 27-Jul-2000	FV GP	230 T	1974	Ran aground in bad weather and rough seas. Engine room subsequently flooded causing power shut down. Crew
Mabulithi Reef intended		18°14.00'S	3	179°18.00'E	rescued by Fiji naval vessel. No salvage operation
					due to severe structural damage.

Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ty	Comments
	Latitude		Longitude	
FV 09-Nov-2000 Harbour	542 C 18°09.00'S	1986 M	Bow of Sun 178°26.00'E	g Kyung No. 507 contacted stern of Direct Kiwi(16281 GT, built 1997). One crewman of Sung Kyung No.507 killed. Master Direct Kiwi states his vessel moored
				and discharging at time.
FJ 12-May-2001	FV GP	0	0	Grounded on reef near uninhabited island in southern Lau. Crew rescued by naval vessel "Kiro". Owner Steve Ayers
12 May 2001		_	178°30.00'W	considering salvage.
VU 01- Jul-2002	Toil	821	1996	Grounded under power on sandy bottom en route Vuda Point to Port Vila. Freed by tug "Maika Tora 4 Jul 02,
01-3ul-2002			177°13.00'E	inspected Vuda Point and proceeded.
US	FV	0	0	Attempts to refloat by South Seas Towage , United
16-Jul-2002	_	5	179°00.00'W	Salvage unsuccessful. Insurer liable for \$525,000 loss and possible costs of removal. Report variously refloated by Seamech Fiji Ltd on 21 Sep 02, and still aground on 23 Oct 02.
FJ 08-Nov-2002	U U 18°07 44'S	0 U	0 178°25 23'E	Cause of sinking unknown. Investigation under way.
	FV 09-Nov-2000 Harbour FJ 12-May-2001 VU 01-Jul-2002 US 16-Jul-2002	Date of Incident Latitude Type Incident Latitude FV 09-Nov-2000 C Harbour 542 09-00'S Harbour 18°09.00'S VU Toil 01-Jul-2002 GP 17°54.82'S 16-Jul-2002 GP 19°30.00'S FJ U 08-Nov-2002 U U	Date of Incident Latitude Type Incident Latitude Severi Incident Latitude FV 09-Nov-2000 C Harbour 542 1986 M M 18°09.00'S 1986 M M 18°09.00'S FJ FV 0 19°30.00'S U 19°30.00'S U 19°30.00'S VU Toil GP U 19°30.00'S 821 M 17°54.82'S M 17°54.82'S 16-Jul-2002 GP T 19°30.00'S T 19°30.00'S T 19°30.00'S	Date of Incident Latitude Type Incident Latitude Severity Longitude FV 542 1986 Bow of Sun 09-Nov-2000 C M 1986 Bow of Sun M Harbour 18°09.00'S 178°26.00'E FJ FV 0 0 0 O T2-May-2001 GP U 19°30.00'S 0 0 T38°30.00'W VU Toil 821 1996 M 17°54.82'S 177°13.00'E 16-Jul-2002 GP T 19°30.00'S 179°00.00'W

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ty	Comments
Location Name		Latitude		Longitude	
Tai Nui French Polynesia Off Papeete	- 21-Dec-1983	FV GP 17°30.00'S	120 T	1973 149°35.00'W	Stranded and sank
Taporo II French Polynesia Reef off Nukutavako Archipelago	- 25-Nov-1984 e, Tuamotu	CG Gp 19°30.00'S	343 T	1963 138°40.00'W	Sprang leak in engine room and beached on reef to save cargo and lives of passengers and crew.
Byron No.16 French Polynesia Tetiaroa Island	- 08-Sep-1988	Rfr GP 17°00.00'S	1872 P	1970 149°00.00'W	Stranded, refloated after cargo offloaded and towed to Japan where repairs effected. Later in service. Hull bottom and steering gear damaged, rudder bent and prop blade twisted. Vessel later trading under name 'Sky Frost'.
Dory 2 French Polynesia Off Makatea Island	FR 13-Aug-2002	FC F 15°50.00'S	348 T	1973 148°15.00'W	Caught fire, sank one day later. Passengers and crew rescued with slight injuries.
Meiho Maru No.7 FSM -	- 22-Apr-1979	FV GP 08°03.00'N	349 P I	1962 146°44.00'E	Stranded, subsequently refloated & taken to Ishinomaki. Repaired & returned to service.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude	Longitude		
Etna FSM	- 25-May-1979	CG GP	3654 M	1972	Stranded, refloated with tug assistance and berthed at Yap.
Yap Harbour	,	09°31.00'N	1	138°08.00'E	
Micro Spirit FSM	- 14-May-1980	CG GP	790 M	1978	Aground, refloated and reported back in service.
Sandbar near Wole		07°22.00'N	1	143°55.00'E	
Curacao FSM	- 16-Jan-1982	FV GP	367 T	1960	Wrecked in heavy weather. Crew rescued. Engine room flooded and tidal. Rudder carrier bolts sheared and rudder
Ngulu Atoll		08°33.00'N	1	137°28.00'E	stock lifted 15cm, skeg set up.
Hinode Maru No.56 FSM	- 12-Sep-1982	FV GP	344 T	1972	Stranded and sank.
Off Truk Island	·	07°25.00'N	1	151°50.00'E	
Kitcho Maru No.28 FSM	- 27-Nov-1982	FV GP	404 T	1968	Wrecked. Extensively damaged. Owners state vessel not to be removed due to extent of damages. Possible cause
Mint Reef		08°05.00'N	I	154°14.00'E	is captain not making sufficient adjustment for fast moving east tide over reef. MFV 'Fukuwa Maru No.1' approached
to					give assistance but also got

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Fukuwa Maru No.1 FSM Mint Reef	- FV 306 28-Nov-1982	1969 W GP 08°05.00'N	Т	. Declared a total lo	oss and not removed. Vessel abandoned.
Conic No.1 FSM	- 30-May-1984	FV GP	908 T	1983	Stranded and presumed to have sank.
Sorol Island	•	08°04.00'N		140°28.00'E	
Tong Wha No.71 FSM	- 17-Mar-1985	FV GP	221 P	1963	Stranded, refloated and taken in tow to Guam. Subsequently sold. Towed to Manila.
Near Ifalik Atoll		07°15.00'N		144°27.00'E	•
Meiho Maru No.17 FSM	- 29-Apr-1985	FV GP	432 P	1972	Stranded, refloated with assistance after several attempts and towed to Ponape. Towed to Hachinohe thence
-	·	05°48.88'N		157°13.35'E	Ishinomaki where repaired and SD. Bottom plate damaged.
Micronesian Comme	rce	-		Ctr	5730 1982 Stranded, refloated and berthed at Yap Pier.
Sailed to FSM Yap,W.C.I.	02-Nov-1988	GP 09°32.00'N	P	138°10.00'E	Palau Islands and thence to Manila. Sustained heavy bottom damage to fuel oil tanks and hull.
Crest 1 FSM	PH 29-Mar-1991	Bulk C 02°43.00'N	0 P	0 154°06.00'E	'Dead in water' following collision with Tenfu (Reefer). No casualties.
-		UZ 43.00 N	ı	134 00.00 E	

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Golden Camia FSM	PH 15-Mar-1992	Bulk O	0 T	0	Sank. Crew abandoned ship due to shifting of cargo (logs) in heavy fog and rain. Crew safely rescued. Oil slick
NE of Yap Island		10°16.00'N	1	139°30.00'E	produced.
Nanshin Maru No.78	JP	FV	19	0	Sank. Crew rescued safely.
FSM -	19-Aug-1992	U T 02°00.00'N		158°07.00'E	
<u>Yujin Busan</u> FSM	PA 27-Feb-1994	Toil F	1550 T	1974	Sank. Attempts to fight a fire in the engine room resulted in the flooding of the vessel. Crew rescued safely.
420 miles south of		00°20.00'N	1	151°40.00'E	the hooding of the vessel. Crew rescued salety.
<u>Oceanus</u> FSM	GR 18-Mar-1994	Bulk GP	38891 P	1993	Ran aground with 70,000 tons of coal. Refloated after part
Wenimong Reef at		07°22.00'N		147°02.00'E	cargo transferred to barges. Proceeded Guam inspection, Ulsan repairs. Satawal residents sued for damages for pollution by coal, spilled oil and garbage dumped during salvage.
Jin Fwu Yi 366 FSM	TA 06-May-1994	U U	0 T	0	Vessel missing. Aircraft reported debris.
-	00-iviay-1994	08°47.00'N	•	151°33.00'E	

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
<u>Dang Delima</u> FSM	PA 16-Jun-1994	CG GP	5903 P	1985	Stranded, refloated and achored at Ponape. Sailed in tow to Busan after repairs. Fuel tanks holed. Oil pollution.
Reef at entrance to	Ponape Harbour	06°40.00'N	1	158°25.00'E	
Ocean Harmony FSM	PA 23-Jun-1994	CG M	3769 U	1973	Disabled and adrift with engine problems.
-	20 00 100 1	08°26.00'N		140°57.00'E	
<u>Deborah</u> FSM	PA 20-Sep-1994	Bulk O	4010 T	1984	Sank. Departed Yap with cargo of logs. Sank but due to cargo drifted 5ft below surface. Crew rescued safely
-		10°23.60'N	1	135°49.20'E	
<u>Valerie</u> FSM	ME 29-Nov-1995	FV H	1127 T	1983	Sank due to crack or holing of hull. All crew rescued.
-		00°39.00'N	1	156°38.83'E	
Mister Bill FSM	- 24-Dec-1996	Other S	196 T	1971	Supply vessel. Took water and sank during typhoon 'Fern'. Crew rescued safely.
85 miles NE of Yap	Island	11°13.00'N	1	165°25.00'E	·
Mina Maru FSM	JP 06-Apr-1998	FV GP	0 U	0	Ran aground. Crew rescued.
West of Fayu Island	•	08°33.00'N	1	151°10.00'E	

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
	FV 0 0 25-Apr-2001		T	adrift and sinking 2	5 Apr. Six crew rescued by Taiwan longline fv Hung Sun Tsai, length 66 ft. No further sightings 1 may, assumed sunk.
<u>Cecilia 1</u> FSM -	- 20-Jun-2002	LC H 08°23.00'N	365 M I	1990 142°36.00'E	Flooding in Engine Room through hole (leak?) Patched by Coast Guard Guam. Cargo petrol in barrels.
Micronesia Sunrise Guam Ibay, off Guam	- 19-Oct-1980	Toil GP 13°32.65'N	3535 P I	1971 144°41.78'E	Reported stranded, refloated and proceeded to Guam for temporary repairs. Sustained a small hole in one tank, fuel transferred to another tank with slight loss of cargo. Oil Pollution.
Bright Peak Guam South of Guam	- 07-Apr-1981	Bulk GP 12°32.00'N	9735 P I	1978 144°42.00'E	Stranded, refloated and diverted to Guam for temporary repairs. Subsequently towed to Onishi for repairs. Returned to service. Cargo wheat.
American Legion Guam Entrance to Apra Hark	- 13-Dec-1985 pour 13°27.00'N	Ctr GP 144°37.00'I	19157 P E	1968	Stranded, refloated with tug aid and entered port where temporary repairs effected. Sailed to Kaohsiung for permanent repairs. 80000 gallons of bunker fuel spilled after an oil tank and cargo hold were ruptured. Oil pollution.
Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	•	Comments
Location Name		Latitude		Longitude	
Toros Bay - Guam On reef	CG 8931 1973 22-Dec-1986	Stranded GP 13°15.00'N	Р	ted and taken to Ap	ora, subsequently taken to Kaohsiung, sold, and broken up. Some extensive damage as vessel stern contacted reef during refloating.

Kotobuki Maru No.1 Guam	- 12-Jan-1988	FV GP	253 U	1966	Stranded during typhoon 'Roy'
Guam		13°28.00'	N	144°32.00'E	
Kaiyo Maru No.5	JP	FV	0	0	Ran aground. Refloated same day.
Guam	28-Jan-1991	GP	M		
Apra Harbour		13°27.00'	N	144°37.00'E	
Glacier Bay	US	Other	0	0	Tank barge. Damaged due to heavy contact with tug.
Guam	07-Jan-1992	С	Р		
Vicinity of Guam		13°52.00'N		145°22.00'E	
Jean Charcot	PA	RV	0	0	Research vessel ran aground while conducting survey of
Guam	18-Mar-1992	GP	M		ocean floor.
Tumon Bay		13°30.00'N		144°47.00'E	
Esso Tees Guam	SI 17-Aug-1992	TIng F	0 P	0	Explosion occurred while vessel discharging pressurised liquefied gas followed by a fire. Immediate action halted
Apra Harbour	3	13°27.00'	N	144°37.00'E	the fire. No injuries.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Seaspan Guam 90 miles NW of Gu	CA 31-Aug-1992 Jam	Brg U 14°34.00'N	0 0	0 143°40.00'E	Barge adrift.
Francisca Guam 15 miles NE of Gu	US 18-Nov-1992	Brg S 13°50.00'N	1075 T	0 145°11.00'E	Deck barge. Broke from tow of tug during typhoon "Hunt" and was lost at sea.
Yasiu Maru Guam Off Guam	- 09-Feb-1994	U H 11°30.00'N	0 T	0 142°55.00'E	Sank after crack developed in hull.
Miya Maru No.88 Guam -	JP 17-Nov-1995	U M 14°07.00'N	349 M	1982 144°23.00'E	Took in water resulting in vessel disabled and drifting. Later towed to Guam.
Anangel Might Guam South west of Gua	04-Nov-1998 im	U M 11°09.20'N	0 M	0 139°15.40'E	Adrift due to engine failure. Later towed by US Navy vessel and then tug Chamorro to Guam
<u>Carolines</u> Guam Near Guam	PA 17-Jan-1999	Bulk S 13°38.00'N	0 T N	0 145°24.00'E	Sank due to bad weather and rough seas. Cargo 6,000 tons of silica sand. Crew rescued safely.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
Fokutoku Maru No.5 Guam	JP 30-May-2000	FV M	119 M	1984	Broke down, adrift 2 days. Tug "Chamorro" towed to Apra for repairs.
7 nmi S Guam		13°08.00'N	١	144°42.00'E	
1st Lt. Baldomero Lo Guam	<u>pez</u> US 05-Aug-2002	RoRo F	32908 P	1985	Fire in engine room. Two crew injured. Vessel disabled. Tug Bei Hai 102 dispatched from Busan
520 nmi NW Guam		15°12.00'N	1	145°42.00'E	
Hangil No.12 High Seas	SK	FV U	0 T	0	Sank.
-		12°45.00'N	1	157°35.00'W	
<u>Flag Mars</u> High Seas	MA 08-Apr-1992	CG M	0 M	0	Damaged rudder. Towed to Guam.
•	·	14°41.00'N	1	157°08.00'E	
Midas Ocean High Seas	HD 02-Jan-1995	Bulk H	0 T	0	Sank. On passage from Nauru to Inchon with phosphate when ingress of water caused vessel to sink. All crew
-	<u> </u>	01°50.00'N		158°50.00'E	safely recued.
Sybarite	US 12-May-1995	U H	0 T	0	Vessel taking in water. Water pumped out and vessel continued on voyage Samoa for Honolulu. Crew later
High Seas -	12-May-1995	10°23.00'N	=	162°03.00'W	picked up when vessel in sinking condition 300 miles from Honolulu. Assumed vessel sank.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
Ming Fong Sheing High Seas -	TA 11-Apr-1997	FV F 15°50.00'N	0 T N	0 133°40.00'E	Caught fire and sank. Nine crew rescued, three missing.
Sapir High Seas 400 nmi N Guam	PA 06-Mar-2000	Toil H 17°31.00'ľ	54980 M N	1990 139°40.00'E	Leak in cargo tank discovered at sea by crew. Cargo redistributed and vessel continued to Honolulu for inspection.
<u>Ji Moon Chun</u> High Seas 648 nmi E Guam	TW 21-Aug-2001	FV F 13°32.00'N	0 T N	0 155°33.00'E	Fire at sea. Vessel burned and sank. Crew rescued by helicopters from USN amphibious assault vessel "Boxer", 40,000 gt, returning from Arabian Gulf.
Chiyo Maru No. 3 High Seas -	JP 13-May-2002	FV F 17°17.00'N	77 T N	1978 151°05.99'E	Fire. Nine crew rescued by another FV. No further sightings, assumed sunk.
Katsuura Maru No. 28 High Seas At Sea	JP 19-Jul-2002	FV H 15°30.00'N	164 T N	1985 164°00.00'E	Sank in open water. Pumps unable to control leak, believed caaused by grounding in Micronesia.
Sea Hawk No.3 indonesia - West Papua	SK 16-May-1991	FV C -	0 T	0 01°36.00'N 137°0	Sank after colliding with Reefer Jia Year No.66. All crew rescued. 06.00'E

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
<u>Lara K.</u> Indonesia?	BA 24-Jul-1991	Bulk M	0 U	0	Lost power.
north of Wetar Islan		07°38.00'S	_	127°10.00'E	
Kwang Myung No.62 Kiribati	- 25-Mar-1980	FV GP	352 T	1968	Wrecked. Crew rescued.
Tamana island	25-Mai-1900	02°30.00'S	-	175°59.00'E	
<u>Nam Chanq</u> Kiribati	- 23-Feb-1982	FV GP	227 T	1971	Wrecked. Crew rescued
Off Starbuck Island	251 651302	05°35.00'S	=	155°35.00'W	
Young Kwang No.5 Kiribati	- 17-Nov-1982	FV GP	243 T	1964	Struck reef, refloated but sank off Christmas Island at 01 41 05N, 156 40 05 W on 22 Nov 82 All crew rescued.
Reef	17 NOV 1302	01°47.00'N	•	157°26.00'W	Sank due to severe leakage of seawater through fractured holes of bottom and one oil tank area.
<u>Fentress</u> Kiribati	- 03-Nov-1983	CG GP	3805 M	1945	Stranded while on loaded voyage from Honolulu to Fanning Island. Refloated and resumed voyage.
Off Christmas Island		02°05.00'N		157°35.00'W	isiand. Renoated and resumed voyage.
<u>Evelyn da Rosa</u> Kiribati	- 03-May-1993	FV GP	966 T	1974	Struck submerged object and subsequently foundered. 18 persons rescued.
-	oo way 1000	02°14.00'N	=	171°10.00'E	To portion resource.

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severit	Year Built ty	Comments
Location Name		Latitude		Longitude	
Aito Kiribati Caroline Atoll	PF 20-Nov-1994	Tug GP 10°00.00'S	0 T	1962 150°15.00'W	Tug grounded on reef while attempting to tow yacht Oracle. Considered a total loss.
Vostochnyy Bereg Kiribati Tarawa Atoll	RU 31-Dec-1994	Rfr GP 01°34.00'N	7856 M	1981 172°56.00'E	Grounded. No damage occurred.
Maasmond Kiribati Approx 415 nautica	- 07-Jan-1997 ıl (500 miles) east	FC F 01°35.00'N	1055 U	1971 179°59.00'E	Drifting without power after fire in engine-room. En route Tarawa to Christmas Island.
of Tarawa Marshall Islands Marshall Islands Off Jemo Island	- 16-Dec-1979	CG GP 10°05.00'N	798 T	1976 169°34.00'E	Wrecked. Salvage attenpts unsuccessful. Constructive total loss.
Tong Wha No.101 Marshall Islands Off Kwajalein Atoll	- 13-Jun-1983	FV GP 08°48.00'N	215 T	1965 167°48.00'E	Wrecked.
Seifuku Maru No.1 Marshall Islands -	- 16-Jan-1994	FV GP 07°06.00'N	119 T N	1985 171°07.00'E	Struck a rock and sank.

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
<u>Victor Eoaeo</u> Nauru	- 29-Jan-1986	FV GD	948 T	1977	Struck reef and sank after moorings parted in heavy weather. 9 crew members rescued.
Reef off Nauru		00°20.00'S	3	167°10.00'E	
<u>Purau</u> New Caledonia	- 07-Aug-1986	Tug GP	247 P	1986	Stranded. Refloated by own power and taken to Poume. Towed to Noumea for temporary repairs and thence
On coral reef	-	19°21.00'S		163°12.00'E	Tonagasaki for permanent repairs. Vessel was on deliver voyage.
Konemu New Caledonia	NC 24-Jan-1997	Toil GP	755 P	1990	Grounded. Refloated with tug assistance. Leakage of light petrol into lagoon.
Reef of Porc Epic, a from Noumea	an island 10 miles	22°01.00'S	8	165°52.00'E	
Contship France New Caledonia	- 14-Feb-1997	Ctr S	16236 M	1993	Minor damage and partial loss of contents of two containers overboard during bad weather. Vessel en route
-		21°15.91'S		169°10.57'E	from Noumea to New York.
Mary D. Princess New Caledonia	NC 02-Aug-1997	FP GP	0 P	0	Grounded. Damaged, repaired, and resumed normal service.
Off Noumea		22°04.00'S	3	166°00.00'E	

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
Nisshin Maru New Caledonia 400 nautical miles of	JP 20-Nov-1998	RV F 20°29.00'S	7569 P	1987 159°54.00'E	Research vessel/fish factory caught fire and drifting without power. No injuries. Later towed to New Caledonia for repairs
Australia	on east coast of	20 29.003	•	139 34.00 E	for repairs.
<u>Padang Hawk</u> New Caledonia	SI 10-Jul-1999	Bulk S	27011 M	1995	Encountered rough seas en route New Caledoni to Townsville and developed a 15 degree list, attributed to
-		22°20.00'S	3	158°20.00'E	liquefaction of nickel ore cargo.essel arrived safely in Townsville.
<u>Seefalk</u> New Caledonia	- 16-Nov-1999	Toil U	639 T	1962	Sank at anchor.
Anchored at Noume		22°17.00'S	=	166°26.00'E	
<u>Komenu</u> New Caledonia	NC 14-Jan-2000	Toil C	0 M	0	Collided with bulk carrier Arctic Trader (14,922 gt, built
Noumea Harbour	14-Jan-2000	22°17.00'S		166°26.00'E	1985) in Noumea Harbour. Damage minor. Reportedly the master of Komenu was drunk.
<u>Lucifero</u> Niue	- 25-May-1999	Other U	0	0	Two crew rescued from sinking yacht.
200 km east of Niue	-	19°00.00'S) }	168°00.00'W	

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Fentress - Northern Saipan Island	CG 3805 1945 15-Nov-1981	5 Stranded GP 15°18.00'N	Р	typhoon 'Hazen'. F	Refloated with assistance after lightening, arrived in Osaka for repairs and then resumed trading.
Nam Sung No.62 Northern sustained	- 20-Jul-1982	FV GP	287 T	1962	Wrecked due to failure of gyrocompass and radar in heavy weather. Vessel left as lies due to heavy damage
Rota Island		14°10.00'N	1	145°09.00'E	
Sun Long No.8 Northern Entrance to Tinian	- 23-Aug-1986 Harbour	Rfr GP 14°57.00'N	3662 P N	1968 145°34.00'E	Stranded while entering harbour. A hold and engine room flooded.
Petro Service Northern On reef off Saipan	- 03-Dec-1986 Island	Sp GP 15°15.00'N	573 U	1968 145°44.00'E	Stranded during typhoon 'Kim'. Vessel a supply ship (O.R.S.V)
Isla Grande Northern Saipan Island	- 17-Mar-1990	Toil GP 15°14.00'N	2915 M	1979 145°42.00'E	Touched bottom whilst manouvering at Saipan Island. Sailed for China. Sustained propeller damage,
Belait Kingfisher Northern Rota Island	- 15-Sep-1990	LC GP 14°06.00'N	253 P N	1974 145°12.00'E	Stranded, refloated with tug assistance, towed to Guam after temporary repair. Towed to Cebu for repairs to hull bottom, tailshaft, propellor, and both rudders.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Tumon 2 Northern 14 miles NE of Sai	MH 06-Oct-1991	CG GP 15°30.00'N	194 T	1970 146°00.00'E	Grounded. Subsequently broke in two and sank during typhoon 'Seth'.
14 IIIICS NE OI CAI	pan	10 00.001	•	140 00.00 L	
Manila Harmony Northern	- 04-Nov-1991	U S	0 P	0	Shifted at sea while sheltering from typhoon 'Seth' resulting in flooding of hold.
Between Saipan ar	nd Tinian Islands	15°06.00'N	1	145°42.00'E	•
<u>Maria</u> Northern	- 20-Feb-1996	CG U	80 U	0	na
Off Rota Island		14°11.00'N	1	145°13.00'E	
Guernsey Express Northern	PH 09-Nov-1996	Other S	4255 T	1967	Livestock carrier (cattle) sank due to bad weather. Crew rescued safely.
-		13°02.00'N	1	144°01.00'E	•
<u>Fidel Jr.</u> Northern	BE 25-Apr-1997	U O	192 P	1961	Sunk due to leaks in starboard tanks while loading containerised cargo. Containers were recovered but
Saipan Dock	_σ,μσ	15°16.00'N		145°44.00'E	severley damaged. Fuel to be removed.
Ob	DA	T.b	747	4077	Opening dead in head acception. Misses discrete as 'lleans. Effects to
<u>Shogun</u> Northern	PA 05-Nov-1997	Tchem GP	717 P	1977	Grounded in bad weather. Minor diesel spillage. Efforts to refloat hampered by typhoon 'Keith'. Cargo offloaded
Rota Island		14°09.00'N		145°08.00'E	before refloated. Proceeded to Rota and thence to Phillipines for repairs.

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
China Progress Northern North of Northern M	18-Feb-2000 ⁄larianas Islands	PA H 17°23.00'N	P N	Bulk0 0 147°56.00'E	Vessel with cargo of copper concentrate, Chile for Japan, sustained hull damage in heavy weather. Flooding in No. 1 hold and ballast tank. Vessel proceeded Guam under tug escort for temporary repairs, thence departed for Qindao 25 Feb.
China Progress Northern	PA 18-Feb-2000	Bulk S 17°23.00'N	0 M 0	0 147°56.00'E	Vessel took in water due to hull damage sustained in heavy storms. Proceeded to Guam under escort from Japanese salvage tug. Cargo copper concentrate.
Greenville III Northern Entrance Saipan Ha	US 27-Aug-2001 arbour	Other GP 15°12.00'N	0 M 0	0 145°42.00'E	Submarine brushed bottom in rough seas on approach to Saipan Harbour. Minor repairs effected Apra Harbour. Greenville was the sub in collision with Japanese training vessel "Ehime Maru" off Diamond Head 9 Feb 01
Bovenhusen NZ? -	CY 02-Jul-2001	U M 33°30.60'S	3186 M	1990 171°02.50'E	Engine breakdown, adrift. Tug dispatched with engineer and parts 4 July .
Bowoon No.7 Palau	- 22-Apr-1980	Toil GP 07°14.85'N	3084 P	1969 134°28.65'E	Stranded. Refloated after jettisoning part cargo and anchored in Koror, Palau. Oil pollution.

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
<u>Bluefin Endeavour</u> Palau	- 05-Jun-1992	FV GP	1010 T	1977	Struck reef (north of PNG) and sank.
Helen Reef		02°55.00'N	1	131°48.00'E	
Blue Diamond Palau	- 28-Aug-1992	U O	0 T	0	Sank.
Vicinity of Helen Re	eef	02°55.00'N	1	131°48.00'E	
<u>Golden Eagle</u> Palau	LI 05-Apr-1998	Toil GP	36865 M	1982	Grounded. Proceeded to Balboa for repairs
Off Palau	·	08°30.00'N	1	134°45.00'E	
<u>Pacific Falcon</u> Palau	PA 21-May-2000	Ctr GP	8132 M	1998	Grounded while on passage from Australia to Japan, carrying 7142 tonnes of containers and copper. Refloated
-	·	07°22.12'N	N	134°22.46'E	by partial unloading and assist from tug Koyo Maru. Anchored and inspected Palau. No immediate repairs required.amage.
<u>Partner</u> PNG -	CY	U GP	0 M	0	Grounded. Refloated and proceeded to Rabaul.

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ty	Comments
Location Name		Latitude		Longitude	
<u>Maluka</u> PNG	- 01-Jun-1977	CG GP	584 T	1950	Vessel stranded on reef in hazy conditions. Iin two rescue attempts 'Sepik Energy' and 'Hebe' both stranded on same
Ragave Point, Cap	oe Vogel	09°41.00'S	3	150°03.40'E	reef and considered total losses. Maluka refloated, anchored at Salamaua Bay, sold and broken up.
<u>Hebe</u> PNG	- 06-Jun-1977	CG GP	296 T	1946	Stranded while attempting to refloat stranded 'Maluka'.
Ragave Point, Car		09°41.08'S		150°03.40'E	Subsequently refloated, towed to Samarai and scuttled off Salamaua.
<u>Carla Manus</u> PNG	- 09-Mar-1979	LC GP	174 M	1970	Stranded. Refloated and resumed service. Damage presumed minor
Reef near Willaum New Britain		05°05.00'S		149°58.00'E	processing name.
Rudolph Wahlen PNG	- 27-Jun-1979	CG GP	115 U	1964	Wrecked. Weather good at time of casualty. Abandoned after attempts to refloat failed. Some cargo saved
Circular Reef	2. 64 16.6	03°26.00'S	_	147°47.00'E	and anompte to remeat randa. Come cargo cavea
<u>ldun</u> PNG	- 02-Aug-1979	CG GP	300 M	1971	Grounded. Refloated under own power.
Dove Island	· · · · · · · · · · · · · ·	09°59.00'S		143°08.00'E	

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
Ambusa PNG	- 02-Aug-1979	LC GP	180 M	1972	Stranded. Refloated& continued on voyage.
Cape Gloucester, N	lew Britain	05°24.00'S	3	148°25.00'E	
<u>Chiang Wei</u> PNG	- 01-Jan-1980	CG GP	3981 P	1979	Stranded. Refloated with assistance after cargo jettisoned & continued service. Probable cause strong current.
Kalili Harbour, New	Ireland	03°26.72'S	3	151°55.00'E	
<u>Dai Wang No. 105</u> PNG	- 15-Jan-1980	FV GP	299 M	1964	Stranded in poor visibility. Refloated by tug and towed to Rabaul.
Coral Island		02°28.00'S	3	149°57.00'E	
<u>Waigani Express</u> PNG	- 04-Jul-1981	CG GP	5084 P	1971	Stranded. Refloated and towed to Port Moresby thence Singapore where sold, renamed 'Papua' and returned to
Off Hood Point		10°09.00'S	5	147°43.00'E	service. Damage to port forward and starboard.
<u>Seiha Maru</u> PNG	- 08-Nov-1982	Tug GD	1033 P	1969	Tug. Stranded after tow wire fouled propellor whilst towing 'Hinode Maru No.8'. Refloated,towed to Sakoshi, sold,
Reef off Rabaul, Ne	ew Britain	04°12.80'S	3	152°30.00'E	broken up.
Manhattan Duke PNG	- 16-Jul-1983	Toil GP	39349 P		Stranded in heavy weather, whilst awaiting pilot. Refloated with tug assistance. Towed to Singapore for repairs.
Basilisk Reef		09°33.00'S)	147°08.00'E	Extensively damaged. Oil pollution.

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
<u>Cosmaris</u> PNG	- 27-Nov-1983	RoRo GP	340 M	1978	Stranded during heavy weather. Refloated with tug assistance and redelivered to owners at Rabaul. Minor
Coral Reef off Ting	won Group	02°37.00'S	3	149°39.00'E	damage.
<u>Longan</u> PNG	- 27-Mar-1984	CG GP	4660 M	1977	Stranded . Refloated with own power but assisted by tug. Minor damage
30 miles south of K Island	ieta, Bouganville	06°33.00'S	5	156°00.00'E	
<u>Tangir</u> PNG	- 17-Jan-1985	LC GD	170 T	1971	Stranded. Capsized and sank after cargo shifted and attempts to refloat
Reef off Port Mores	sby	09°32.00'S	8	147°07.00'E	·
Moale Chief PNG	- 28-Feb-1985	LC GP	262 P	1981	Stranded. Taken to slipway at Port Moresby, repaired and returned to service. Mechanical damage
Reef at Gadaisu Po	oint, Orangerie Bay	10°35.00'S	3	149°37.00'E	
Bow's Brother	_	CG	4719	1977	Stranded after dragging anchor in heavy weather, reflected
PNG Between Rabaul ar	23-Jun-1985 and New Ireland	GD 04°04.00'S	Р	1977 152°26.00'E	Stranded after dragging anchor in heavy weather, refloated with tug aid, towed to Rabaul thence Kobe where repairs effected, returned to service. Mechanical damage.
Detween Nabadi ai	ia i vew ii ciana	07 07.00 0	,	102 20.00 L	chocod, returned to service. Mechanical damage.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Ok Tarim PNG	- 19-Aug-1985	Tug GP	126 P	1982	Stranded when main towing line became entangled in port propeller. Taken to port where surveyed and repaired and
Off Port Moresby		09°32.00'S	3	147°07.00'E	returned to service. Slight damage.
Bright Ace PNG	- 11-Oct-1986	RoRo GP	7666 P	1978	Stranded. Refloated and taken to Port Moresby, then to Ulsan and Japan. Repaired and returned to service.
33 miles NE of Cap	e Nelson	08°35.00'S		149°40.00'E	Sustained mechanical damage.
Smilax PNG	- 03-Jan-1987	CG GP	3810 M	1982	Stranded. Refloated and proceeded to Tufi Anchorage for inspection. Returned to service. Minor damage.
-		08°47.00'S	3	150°11.00'E	
<u>Witbridge</u> PNG	- 02-Mar-1987	LC GP	718 P	1977	Stranded. Refloated and towed to Cairns for repairs then returned to New Britain. Mechanical damage.
20 miles east of Ca	pe Ward Hunt	08°00.00'S	3	148°30.00'E	
<u>Huris</u> PNG	- 05-Oct-1987	LC GP	354 M	1977	Stranded whilst unloading in heavy swell. Refloated with tug assistance and towed to Rabaul. Minor damage.
Lihir Island		03°06.00'S	3	152°39.00'E	
Sun Island PNG	- 09-Mar-1989	CG GP	3931 M	1974	Stranded. Refloated without assistance and towed to Port Moresby for temporary repairs. Minor damage
Off Woodland Islan	d	09°09.78'S	3	152°24.25'E	· · · · · · · · · · · · · · · · · · ·

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Kim Lien PNG	- 18-Jul-1990	CG GD	6020 P	1977	Stranded after sustaining engine failure. Refloated with tug assistance and towed to Port Moresby.
Reef 2 miles off Po Harbour entrance	ort Moresby	09°32.00'S	3	147°07.00'E	
Glomaris PNG	- 26-Jul-1990	LC GP	371 P	1981	Stranded. Capsized and sank. Subsequently raised and repaired. Vessel holed.
Off Jacquinot Bar, I	New Britain	05°40.00'S	3	151°36.00'E	
Steel Rover PNG	PG 15-Mar-1991	Other U	0 U	0	Logging barge. Reported drifting without anyone on board.
south west of Boug		07°50.00'S		154°00.00'E	
Simbang PNG	PG 04-Sep-1991	FC GP	0 T	0	Sank after being hit by a freak wave which drove it onto a reef before capsizing. 9 people died and 24 missing.
Vitiaz Strait, near P northern PNG	ort Sialum,	05°50.00'S	3	147°32.00'E	
AdhigunaNugraha 1 PNG	IN 06-Sep-1991	CG GP	4928 M	1980	Stranded in heavy weather. Refloated with tug assistance and towed to Rabaul then Singapore for repairs. Minor
Reef near Cape Se		02°19.32'S		150°51.10'E	damage. Log carrier

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Costa de Marfil PNG	SK 09-Oct-1991	U C	807 M	0	Collided with Atlantis (1,427 tons).
-		05°34.00'S	3	156°01.00'E	
Shilla Pioneer PNG	SK 21-Nov-1991	FV C	0 P	0	Collided with Fung Kuo No.736. Hull sustained damages.
-		02°30.00'N	1	145°30.00'E	
Paradise Ocean PNG	PA 20-Feb-1992	Bulk GP	0 M	0	Grounded. Refloated under own power.
-		10°21.33'S	3	151°01.58'E	
Chemlong PNG	KO 24-Mar-1992	FV O	0 T	0	Sank
100 miles north of	Manus Island	00°14.00'S	3	146°54.00'E	
Sheng Fu No.16 PNG	- 06-May-1992	FV GD	311 T	1972	Wrecked after sustaining steering failure.
-	.,	09°49.00'S	3	142°12.00'E	
Hand Cheong PNG	PA 07-May-1992	CG GP	5030 P	1978	Stranded in strong wind and current. Refloated and towed to Rabaul for repairs. Cargo logs.
Reef on approach Ireland	•	03°27.60'S	6	152°13.70'E	

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
Ayu Permata PNG Reef at Karu, New	IN 07-May-1992 Ireland	U GP 03°52.65'\$	5030 P	1978 153°08.10'E	Grounded. Holed. Subsequently towed to Rabaul for temporary repairs
Madang Coast PNG -	PG 07-Nov-1992	U F	0 P	0	Engine room fire while on voyage from Lae to Oro Bay. Fire extinguished and vessel returned to Lae. Extensive damage. NO injuries.
Carlina PNG Natera Reef, on ap Passage	PA 30-Nov-1992 oproach to Basilisk	CG GP 09°33.00'S	0 M S	0 147°07.70'E	Stranded. Refloated by tug. Minor damage.
Arktis Ocean PNG River Fly	- 04-Mar-1993	CG GD 08°25.00'5	1598 P	1987 143°10.00'E	Touched bottom after log caught in propeller. Cargo copper concentrate.
<u>Pixy May</u> PNG	PA 22-Mar-1993	CG GP 06°19.00'S	2820 M	1986 149°52.00'E	Stranded. Refloated and towed to Rabaul for repairs. Vessel sailed for Japan.
Olympus Kim PNG -	SK 06-Apr-1993	U C 00°22.00'\$	0 P	0 151°30.00'E	Collided with Reina No.101. Structural damage.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
Armstrong PNG	PA 13-Aug-1993	CG GP	6719 P	1970	Ran aground while entering port. Arrived Rabaul with salvor assistance. Subsequently sailed to Aland and broken
Port Aumo, West N	ew Britain	06°58.00'S	5	148°36.00'E	up. Hull bottom holed. Cargo logs.
<u>Kris</u> PNG	PG 19-Aug-1993	RoRo U	420 T	1972	Capsized and sunk. Two passengers and a crewman died.
near Samuda Island	d, West New Britain	05°24.00'S	3	149°01.00'E	
_					
<u>Tenyu Maru</u> PNG	JP 17-Oct-1993	U GP	3703 U	0	Ran aground while entering port.
Entrance of Port Work Britain Is.	asum, SE coast	06°19.06'S	;	149°51.14'E	
Tropic Wind PNG	- 11-Nov-1993	CG S	0 T	0	Sank in heavy weather and rough seas caused by Cyclone "Jeana"
-		25°58.00'N	l	131°32.00'E	
Kwang II No.3 PNG	SK 01-Mar-1994	FV U	286 T	1963	Sank. Crew abandoned sinking vessel and were safely rescued.
Gulf of Papua, 185 Moresby	km NW of Port	08°40.00'S	;	145°35.00'E	

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Samsun Brave PNG	- 06-Mar-1994	FV GP	1247 T	1983	Grounded.Subsequently slipped off reef, capsized, and sank. Crew rescued. 10 islanders that boarded the vessel
Reef off Carteret Is Solomon Islands	sland, North	04°42.00'S	8	155°26.00'E	to remove goods died when vessel capsized and sank.
<u>Papuan Chief</u> PNG	HK 25-Jun-1994	Ctr GP	7914 M	1991	Grounded. Refloated with assistance and proceeded to Alotau for inspection. Sailed to Singapore for repairs.
East Island, Bonvo	uloir Islands	10°23.00'S	3	152°07.00'E	
<u>Dasa Sebelas</u> PNG	PA 13-Oct-1994	U GP	0 P	0	Ran aground. Towed by tug to Port Moresby.
Star reef area		08°29.00'S	3	149°35.00'E	
<u>Ocean Yuri</u> PNG	PA 07-Jan-1995	CG GP	0 P	0	Grounded. Refloated and towed to Madang for repairs. Cargo logs.
Off south coast of I	New Britain	06°24.00'S	3	149°38.00'E	
Shoei No.2 PNG	PA 24-May-1995	CG GP	3007 M	1982	Grounded. Refloated.
Off New Britain	24-May-1333	06°05.00'S		148°34.00'E	
Grand Fortune PNG	PA 25-Sep-1995	CG GP	7913 P	1976	Ran aground. Refloated with assistance and proceeded to Lae for repairs. Forepeak holed.
On reef	·	06°18.00'S	3	149°50.90'E	· ·

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Armada Kasturi PNG Reef off Sauren, off	ML 16-Oct-1995	CG GP 04°34.10'5	6784 U	1975 168°17.39'E	Grounded. Cargo logs.
Neel oil Saulell, oil	West New Dillain	04 34.10 0	,	100 17.39 L	
<u>Pera</u> PNG	- 09-Mar-1997	LC S	310 T	1969	Sank in bad weather due to Cyclone 'Justin". 6 of 8 crew rescued.
S tip of New Ireland St George	Prov., SE of Cape	05°00.00'S	6	153°02.00'E	
Orange Wave PNG	SI 14-Aug-1997	Other M	7551 P	1983	Engine breakdown. Towed to Madang Harbour by ferry. Vehicle carrier.
-		05°10.00'S	8	146°00.00'E	
Elfreide PNG	PG 07-Oct-1998	FV GP	0 T	0	Grounded. Crew rescued safely. Attempts to refloat abandoned.
Reef near Basilisk F		09°32.27'S	8	147°08.07'E	
Star Sun PNG Jacquinot Bay, Eas	- 09-Dec-1998 st New Britain	CG GP 05°42.80'S	6399 T	1975 151°46.00'E	Sank. Initially ran aground on reef at Wasum Bay, West New Britain. Pulled off and towed to Rabaul when sank. Crew rescued.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
Bao Ji Shan PNG	PA 21-May-2000	CG GP	0 M	0	Grounded. Cargo logs
Reef outside entrar	nce to Port Moresby	09°32.00'S	5	147°06.00'E	
Gazelle Coast PNG	HK 14-Jun-2000	U GP	4292 U	1984	Aground.
Isulailai Point		10°33.60'S	3	150°42.40'E	
<u>Ligaya</u> PNG	HN 08-Aug-2000	CG M	4339 M	1982	Mechanical breakdown forced vessel to anchor after leaving Port Moresby for Kaohsiung. Towed to Port
-	-	10°46.00'S	8	141°32.00'E	Moresby, repaired and continued voyage.
Anax PNG	MT 14-Aug-2000	Bulk M	18392 M	1979	Dissabled by engine problem. Carrying (ore?) concentrate and fish meal for Thailand. Towed to Port Moresby
At Sea		10°20.00'S		157°10.00'E	· · · · · · · · · · · · · · · · · · ·
Coral Trader PNG	BS 25-Jan-2002	RoRo GP	4887 P	1978	Grounded, with punctured forward double bottom. Ballast tanks. Freed with tug assistance, repaired and resumed
-		10°14.33'S	3	150°56.27'E	service.
<u>Irina 2</u> PNG	MT 29-Jul-2002	Toil GP	15063 U	1983	Tug from Smit Salvage dispatched to aid crude oil tanker aground. Outcome unknown.
Oro Bay		08°53.00'S	3	148°29.00'E	-

Vessel Name Country of Incident	Flag Date of Incident	7.	GRT Severi	Year Built ty	Comments
Location Name		Latitude		Longitude	
Kimbe Queen PNG Kimbe	PG 01-Oct-2002		156 M	1989 150°09.00'E	Vessel grounded on leaving Kimbe on regular route to Rabaul. 180 passengers transferred to Rabaul Queen. Vessel refloated 4 days later, returned directly to service. Grounding attributed to lack of navaids.
Polynesia Samoa East Reef, Off Apia	- 09-Sep-1988 ı, Upolu Island		10774 M	1979 171°45.20'W	Stranded, refloated without assistance, returned to Apia, sailed for Long Beach, CA for temporary repairs. Resumed service. Damage confined to an area aprrox. 2.5 m in length in way of bulbous bow.
Queen Salamasina Samoa Apia	- 03-Feb-1990		714 P	1977 171°45.00'W	Stranded during Cyclone Ofa. Refloated and towed to Nelson. Repaired and vessel returned to Samoa.
Jin Shiang Fa Samoa Reef at Rose Island	TA 14-Oct-1993 d	FV 3 GP 1 14°33.00'S	363 T	1985 168°09.00'W	Struck reef near island which is a bird sanctuary. Created diesel spill. Removed and sunk in deep water.
Agnui 1 Samoa 160km (86 nmi) we	SB 07-Oct-2001 est of Savai'i		0 M	0 174°18.00'E	Mechanical breakdown, drifted 10 days before being located by Orion aircraft from (??). Six crew well, rendezvous and presumed towed by sister vessel Agnui II.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severit	Year Built ty	Comments
Location Name		Latitude		Longitude	
Greenville III Seychelles?	SI 05-Nov-1993	Tug M	0 U	0	Tug with barge in tow disabled and adrift.
-		02°06.00'N	N	073°05.00'E	
<u>Pacific Trader</u> Solomon Islands	- 23-Mar-1979	Toil GP	970 M	1972	Stranded. Refloated without assistance and proceeded to Honiara for survey. Tanker?
Viru Harbour		08°32.00'S	3	157°44.00'E	·
Pacific Voyager Solomon Islands	- 20-Jun-1979	Toil GP	674 P	1970	Stranded. Refloated with tug assistance and repaired at Rabaul. Mechanical damage.
Gizo Harbour		08°06.00'S	3	156°51.00'E	•
<u>Yu Hsing</u> Solomon Islands	- 02-Jul-1979	FV GP	0 P	0	Stranded. Refloated and taken to Honiara for repairs. Mechanical damage.
-		05°08.00'S	3	159°09.00'E	
Solomon Fisher Solomon Islands	- 16-Sep-1979	FV GP	121 P	1979	Stranded. Refloated and repaired.
Reef at Tulagi	10 000 1010	09°06.00'S	=	160°09.00'E	
Tenryu Maru No.22 Solomon Islands	- 11-Mar-1980	FV GP	194 T	1969	Stranded. Declared a constructive total loss.
Soloman Sea		08°00.00'S	3	154°40.00'E	

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severit	Year Built ty	Comments
Location Name		Latitude		Longitude	
Soltai No.6 Solomon Islands	- 08-Aug-1980	FV GP	103 M	0	Stranded. Refloated with assistance and towed to Tulagi. Minor mechanical damage.
Off Munda lighthous Island	se, New Georgia	08°20.00'S	3	157°13.00'E	
<u>lu-Mi-Nao</u> Solomon Islands	- 13-Aug-1980	FC GP	518 M	1965	Stranded on reef. Refloated, repaired and returned to service. Slight damage.
Reef		08°55.00'S	3	159°10.00'E	
<u>Mikolaj Rej</u> Solomon Islands	- 16-Aug-1983	CG GP	9397 P	1969	Listed after stranding. Discharged cargo and refloated. Pilot error was cause.
Honiara Harbour		09°26.00'S	3	159°58.00'E	
<u>Hanlim Master</u> Solomon Islands	- 15-Feb-1984	Bulk GP	9808 P	1969	Stranded whilst manoeuvring close to shore to load logs. Oil tank ruptured causing oil pollution . Refloated
Beach 3 miles west San Cristobal	of Taware Point,	10°22.60'S	3	161°46.50'E	
Ann Solomon Islands	- 03-Mar-1985	CG GP	262 M	1958	Stranded in heavy weather. Refloated with no damage. 1 crew missing.
1 mile E. of Point C	ruz, Honiara	09°25.00'S	3	159°56.00'E	

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
Soloman Princess Solomon Islands On rocks approx. 1 Cruz, Honiara	- 03-Mar-1985 mile E. of Point	FP GP 09°25.00'S	121 T	1969 159°56.00'E	Wrecked in heavy weather
Regina M Solomon Islands Honiara	- 19-May-1986	CG GD 09°25.00'S	500 U	1956 159°57.00'E	Stranded after dragging acnhors during cylcone Namu. Broken up in situ.
<u>Island Trader</u> Solomon Islands Rua Ndika Reef	- 20-Jan-1988	CG GP 08°43.00'S	199 P	1969 159°56.00'E	Stranded. Refloated and taken to shipyard for repairs.
<u>Camphor</u> <u>Solomon Islands</u> River Enoghae	LI 19-Aug-1990	U GP 08°10.00'S	0 M S	0 157°18.00'E	Grounded. Refloated.
Larix Solomon Islands Aruraha Bay, Makir Cristobal	PA 17-Apr-1991 a Island, San	CG GP 10°26.00'S	3810 M	1981 161°27.00'E	Touched bottom whilst entering Bay. Towed to Honiara. Minor mechanical damage.

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Soltai No. 25 Solomon Islands	SI 04-Jul-1991	FV S	64 T	1969	Sank due to rough seas and strong winds whilst on journey from fishing ground to Gizo. 6 crew still missing.
-		08°27.00'S	3	156°39.00'E	
Island Trader Solomon Islands	SI 17-Feb-1992	CG GP	199 T	1969	Stranded during cyclone Daman. Refloated and berthed at Honiara. Scuttled.
Ranadi Beach		09°25.00'S	3	159°57.00'E	
<u>Liapari</u> Solomon Islands	SI 17-Feb-1992	U GP	55 P	1984	Grounded during sudden squall. Severly damaged.
Ranadi Beach, Hor	niara	09°25.00'S	3	159°57.00'E	
Harmonica Solomon Islands Point Cruz	- 17-Feb-1992	Other GP	0 M	0	Yacht. Grounded. Later refloated.
Princess II Solomon Islands	SI 27-Jul-1992	FP GD	133 T	1963	Sustained engine trouble and stranded. Subsequently sank. All passengers and crew rescued.
Florida Islands		09°09.00'S	3	160°23.00'E	·
<u>Tropical Damsel</u> Solomon Islands	PA 13-Oct-1992	CG GP	5451 M	1985	Touched bottom. Towed to Noro for temporary repairs. Rudder damaged.
Wilson Harbour		07°49.00'S	3	157°18.00'E	-

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ity	Comments
Location Name		Latitude		Longitude	
<u>New Asia</u> Solomon Islands	TA 01-Jan-1993	CG GP	0 U	0	Ran aground in bad weather caused by cyclone "Nina".
Kalena Bay entrand	e, New Georgia	08°21.40'S	3	157°38.80'E	
Solomon Catcher Solomon Islands	- 14-Feb-1993	Bulk U	27 T	1984	Sank after taking in water. Crew rescued.
-		08°33.00'S	3	158°47.00'E	
<u>Pelawan</u> Solomon Islands	- 21-Apr-1993	CG GP	4815 P	1975	Struck reef whilst manoeuvring and sustained damage to rudder and propeller. Towed to Noro.
Sumberged reef at	Keneko	08°28.00'S	3	157°16.00'E	
<u>Qena</u> Solomon Islands	EG 23-Dec-1993	Bulk H	0 U	0	Taking in water
Near Solomon Islan	ds	13°27.00'S	3	161°51.00'E	
Kinabalu Limabelas Solomon Islands	ML 15-Mar-1994	CG GP	4685 T	1977	Grounded. Efforts to remove vessel have failed.
Entering Kenelo, we Islands		07°53.73'S		157°56.12'E	
World Discoverer Solomon Islands	LI 30-Apr-2000	CL GP	3724 T	1974	Beached after hit unchartered reef. No injuries reported.
Sandfly Passage	·	09°01.00'S	3	160°07.00'E	

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
<u>Sea Star</u> Solomon Islands	GE 16-Dec-2000	CG GP	6601 U	1977	Log vessel grounded on reef, still aground 22 dec 02.
Reef outside Munda Solomons	a, Western	08°22.89'S	5	157°13.81'E	
Anyamanii Solomon Islands logs.	- 04-Mar-2002	CG O	4581 M	1973	Piracy. Vessel boarded and crew robbed by 10 armed men, four with guns. Proceeded to Malaita for cargo of
Honiara		09°25.00'S	3	159°57.00'E	
<u>Hua Di</u> Solomon Islands	MT 03-Oct-2002	CG G	10932 P	1977	Developed steering gear problems, grounded. Cargo approximately 7000 cubic meters logs. Vessel refloated
-	00 00. 2002	08°47.30'S	5	157°55.70'E	without assistance, anchored. Tug Hua Ji dispatched from China to tow Hua Di to Shanghai for repairs.
<u>Tai Yang No.103</u> Tokelau	19-Feb-1978	FV U	133 U	1967	na
Reef on S.W. side of		08°34.00'S		172°28.30'W	
Nam Hae No.217 Tokelau	- 09-Apr-1978	FV GP	159 U	1965	Stranded in poor visibility
Off Atafu Island	•	08°31.00'S	3	172°30.00'W	

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severi	Year Built ty	Comments		
Location Name		Latitude		Longitude			
Sunlight No.22 Tokelau	- 20-Jun-1979	FV GP	291 P	1963	Stranded. Refloated and towed to Suva. Repaired and returned to service. Moderate damages		
Nukunono		09°10.00'S	3	171°50.00'W			
<u>Ai Sokula</u> Tokelau	- 26-Feb-1981	CG GP	400 T	1961	Wrecked. Salvage attempts abandoned due to low value of vessel and damage to hull. Cargo plundered by islanders.		
Reef off Fakaofo A	toll	II 09°19.55'S 171°12.90'W		171°12.90'W			
Young Kwang No.3 Tonga	- 23-Feb-1987	FV GP	184 T	1965	Wrecked		
Coral Reef		15°57.00'S	3	173°43.00'W			
<u>Golden Glow</u> Tonga	US 03-Feb-1998	U F	959 T	1967	Fire started on board forcing crew to abandon ship. Crew later rescued. Position reports conflict; 175o00.00'E		
200 miles south of	Tonga	21°59.56'S	3	175°00.85'W	probably in error, corrected to W.		
<u>Paragon 3259</u> Tonga	NZ 27-May-2002	FV M	0 M	0	Trawler adrift due to engine problems. Located by RNZAF Orion aircraft on routine patrol. Towed to Tonga by fishing		
At Sea	•	20°02.00'S	3	176°00.00'W	vessel Southwind.		
Nam Hae No.203 Tuvalu	- 10-Nov-1978	FV GP	159 P	1965	Grouned. Refloated and repaired at Suva. Mechanical damage.		
Nanumanga		06°20.00'S	3	176°17.00'E			

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built rity	Comments
Location Name		Latitude		Longitude	
Aoi Maru Tuvalu	- 18-Jan-1979	CG GP	223 P	1972	Stranded. Refloated without assistance and sold. Casualty occurred in heavy weather. Taken to Suva.
Funafuti Island		08°31.00'S	o i	179°08.00'E	
<u>Sieh Tsin Jung</u> Tuvalu	- 08-Feb-1981	FV GP	187 T	0	Stranded. Left-as-Lies. Major mechanical damage. Charged for illegal fishing by Tuvalu government.
Nukufetau		08°00.00'S	3	178°30.00'E	
<u>Sisco</u> Tuvalu	- 20-Apr-1981	CG GP	481 T	1949	Wrecked. Bottom extensively damaged. Attempt to refloat unsuccessful. Casualty occurred.
Vaitup Island		07°28.00'S	3	178°41.00'E	
<u>Jeanette Diana</u> Tuvalu	US 21-Apr-1993	FV F	0 T	0	Main engine blew starting a fire. Crew abandoned vessel and were later rescued. Vessel sank 50 miles east of
800 miles NNE of F		05°00.00'S	•	178°00.00'E	Tuvalu.
Ryoyu Maru No.8	-	FV	134	1973	Stranded after an electrical fault. Owners abandoned
USA - Palmyra On Kingman reef 4 Palymyra Island	22-Nov-1979 0 miles NW of	GD 06°25.00'N	P	162°26.00'W	vessel to salvors who refloated and effected repairs. Renamed Jucy and used as an auxillary salvage vessel by salvors.
<u>Hui Feng No.1</u> USA - Palmyra	- 14-Jun-1991	FV GP	280 P	1969	Stranded. Crew rescued. Diesel fuel leakage.Oil pollution
Palmyra Island		05°53.00'N	=	162°05.00'W	

Vessel Name Country of Incident	Flag Date of Incident	Type Type Incident	GRT Sever	Year Built ity	Comments
Location Name		Latitude		Longitude	
Shanta Shibani USA - Wake Island Wake Island	- 1 25-Jan-1984	Bulk GD 19°17.00'N	15387 P N	1971 160°37.00'E	Stranded on rocks after moorings broke in heavy weather. Refloated and taken to Guam and thence to Ulsan where temporary reparis effected.
<u>Kalili</u> Vanuatu Palikulo Bay, Espiri	- 16-Jan-1985 tu Santo Island	FC GP 15°29.00'S	227 T	1961 167°14.00'E	Stranded. Subsequently sank following cylcones Eric and Nigel.
Federesen Nalkutan Vanuatu Segond Channel, o	- 18-Jan-1985 ff Espiritu Santo	CG GP 15°33.00'S	341 T	1958 167°08.00'E	Wrecked during cyclone Nigel.
<u>Fetukai</u> Vanuatu Tanna Island	- 16-Jun-1987	CG H 19°30.00'S	115 P	1971 169°20.00'E	Took water and beached. Refloated after temporary repairs and taken to Port Vila.
Lublin II Vanuatu Santos Port	PO 18-Nov-1992	U U 15°31.00'S	0 P	0 167°10.00'E	Vessel leaked oil into port causing pollution
Matissimo Vanuatu Santos Port	VU 18-Nov-1992	U M 15°31.00'S	0 P	0 167°10.00'E	Vessel leaked oil into port causing pollution

<u>Vessel Name</u> Country of Incident	Flag Date of Incident	Type Type Incident	GRT Severit	Year Built y	Comments
Location Name		Latitude		Longitude	
<u>Latua</u> Vanuatu	- 08-May-1999	FP S	0 T	0	Vessel went missing during heavy storms. 25 passengers and crew on board.
Between Port Vila	and Shepherd	17°10.00'S	5	168°40.00'E	
<u>Fetukai</u> Vanuatu	- 16-Jun-1987	CG H	115 P	1971	Took water and beached. Refloated after temporary repairs and taken to Port Vila.
Tanna Island		19°30.00'S	3	169°20.00'E	
<u>Lublin II</u> Vanuatu	PO 18-Nov-1992	U U	0 P	0	Vessel leaked oil into port causing pollution
Santos Port	101101 1002	15°31.00'S	•	167°10.00'E	
<u>Matissimo</u> Vanuatu	VU 18-Nov-1992	U M	0 P	0	Vessel leaked oil into port causing pollution
Santos Port	10-1100-1992	15°31.00'S	-	167°10.00'E	
<u>Latua</u>	- 00 May 4000	FP	0	0	Vessel went missing during heavy storms. 25 passengers
Vanuatu Between Port Vila a Islands	08-May-1999 and Shepherd	S 17°10.00'S	T }	168°40.00'E	and crew on board.

5 APPENDIX 5: RISK ANALYSIS METHODS AT THE REGIONAL AND EEZ SCALES

Several map layers were required to create the grounding and collision potential maps. These included the vessel traffic route and volume map, as well as the contextual map layers: reefs and shorelines. The method described here involves two distinct processes: one for the grounding hazard map and one for the collision hazard map. Both maps use a separate 'thematically-shaded grid' layer to store information processed from the traffic and context layers. For example: the product of the number of routes in a grid area and the volume of traffic in the area is stored for each grid cell. This information is then coloured for each grid cell as a low, moderate or high collision hazard.

5.1 Grid Creation

First, a grid was created covering the study area. Each grid square has a data field named Zero_depth. If this field is set to '1' then a grounding hazard exists in the form of a reef or a shoreline contour. This grid need only be created once. It is re-used each time a new thematic grid map is required for either collisions or groundings.

Step 1. Create a grid of regions in MapInfo—one degree x one degree in size.

Use the MapInfo Grid Maker add-in tool.

Step 2. Count the reefs and shorelines that intersect with the grid cells

Use the MapInfo Update Column function. The OneDegreeSquares table is preprocessed using the geographic join where intersects and where within from the reefs and auspol tables to the grid table. The Zero_depth field in the grid table is then set to 1 or 0 if there is a grounding danger or not, respectively. Steps 1 and 2 need never be repeated unless the reefs or auspol maps are updated.

5.2 Grounding potential thematic map

In order to cover the entire south pacific study area, the resolution of this map is one degree or 60 nautical miles square. Grounding potential is thematically mapped as the product of the existence or not of a reef or shoal within a one degree grid cell and the traffic volume.

Step 1. Update the Grounding_risk field in the grid cells with the product of the Zero_depth and the traffic count.

1

Use the MapInfo Update Column function.

Step 2. Create the thematic map using the Grounding_risk field

Use the MapInfo Create Thematic Map function.

5.3 Collision potential thematic map

Collision potential is thematically mapped as the product of the count of traffic routes within a one degree grid cell and the traffic volume. This function is intended to associate a higher collision potential with multiple routes in close proximity.

Step 1. Count the vessel routes that intersect with the grid cells

Use the MapInfo Update Column function. The grid map is processed using the geographic join where intersects with the table Sroutes. The field Count_routes is set to the count of the number of vessel routes that intersect with each grid cell.

Step 2. Update the Collision_risk field in the grid cells with the sum of total traffic frequency data for all routes in Sroutes that intersect with the grid cells

Use the MapInfo Update Column function. The grid map is processed using the geographic join where intersects with the table Sroutes. The field Collision_risk is set to the Sum(TotalFreq) of of SRoutes that intersect with each grid cell.

Step 3. Update the Collision_risk field in the grid cells with the product of the count of routes and the total traffic count

Use the MapInfo Update Column function. The grid map is processed by setting Collision_risk = Count_routes x Collision_risk.

Step 4. Create the thematic map using the Collision_risk field

Use the MapInfo Create Thematic Map function

6 APPENDIX 6: SAMPLE FORMS

COUNTRY DATA SHEET

PACPOL RA1: Marine Risks Assessment

COUNTRY:

(one row omitted_

Reward for return, if lost to:

Edward Anderson Marine Sciences PO Box 2125 Sidney, BC anderson_e@coastnet.com or (Feb – Mar 2001) c/o Institute of Applied Sciences, USP, PO Box 1168, Suva, Fiji (679) 313 900

or Sione Tu'itupou Fotu POBox 2461, Nuku'alofa, Tonga (676)22479 stfotu@kalianet.to or GeoInfoSolutions, 10352 Arbay Close, Sidney, British Columbia, Canada V8L 4S2 (250) 656-7170, bjudson@geoinfosolu tions.com

MA 100 00//EDN	MENT AGENGIEG DO	DT0 F1011F		- A 1
MAJOR GOVERN	MENT AGENCIES: PO	RIS, FISHE	RIES, ENVIRONME	:N I
Agency, Department	t, Contact	Addre	ess, Phone, fax, email	Contacted?
Ministry				(When, who)
•				, ,
/				
(one row omitted)				
		l .		
MA IOD DODTS S	ERVING INTERNATION	IAI OP IAI	EDICI VND CHIDDI	NG
		AAL OIL III I		
Port	General description		OPTIONAL:	Info source, year
			Cargoes handled,	to which it applies?
			approx annual	
			volume	

COUNTRY DATA SHEET p2

	COUNTRY:		_			Page	of
	ACTIVE SHIPPING	G LINES SERVING C	OUNTRY, VESSELS ove	er 200 GRT, and V	ESSEL CHARACTE	RISTICS	
Shipping lines active in country (international lines and any in country with vessels over 200 GRT; distant-water fishing vessels may be grouped- e.g. longline FV, 200-400 GRT)			Vessels (Vessels that have called in one recent year, especially those that repeat calls on schedule)				
	Line name, flag	Agent or contact	Address	Vessel name(s)	Type (container, bulk cargo, oil tanker, LNG tanker, passenger/cargo ferry, etc.)	Tonnage GRT? DWT?	Speed, kn (if known)

(use additional sheets as necessary)

PORT DATA

PACPOL RA1: Marine Risks Assessment

Edward Anderson Marine Sciences anderson_e@coastnet.com c/o Institute of Applied Sciences, University of the South Pacific PO Box 1168, Suva, Fiji email

phone (679) 313 900 fax (679) 300 373

Country	Port (separa country)	te shee	Page _	_ of		
Contact(s) for this port Data source person, positio		Mail		Phone		
country")	11 (01 300	IVIAII		<u>Fax</u>		
Department, agency or o	company			Email		
Data source person, positio	n	Mail		Phone		
Department, agency or company				<u>Fax</u>		
				<u>Email</u>	_	
Traffic Patterns						
Vessel (or Line of similar vessels from Country Sheet) (distant waters fishing vessels may be grouped, as in examples)	Inbound from		Outbound to		Frequency (per year)	
Examples	examples		examples		examples	
(three rows deleted)						
(use additional sheets a Port: (continued) General practices (this				Page c		

Ballast/deballast (Do vessels deballast to enter port? Which types of ve	essels, and where?)
Solid waste disposal (Do visiting vessels unload solid waste at this por	t? Dump at sea nearby?)
Sewage (Do vessels discharge sewage to harbour or lagoon?)	
Further impressions (Bilge pumping, lube oil disposal, etc.)	
and the process of th	
Hazards to navigation (optional section - any places of speci	al danger to ships?)
Near port	
Within country EEZ on frequently traveled routes	
Environmentally sensitive areas at risk to pollution from ship	os (optional section)
Near port	
Within country FF7	
Within country EEZ	
Hazard/sensitive location notes and sketches - use additional	l pages as necessary
(charts, sketches, or rough drawings will help us understand	
, , ,	,
Date recording nates (places leave this last agatism blank)	
Data recording notes (please leave this last section blank) Comments/verifications	Data recorded by
Comments/verinications	Data recorded by
	Date
I	

SHIPPING LINE DATA

PACPOL RA1: Marine Risks Assessment

Edward Anderson Marine Sciences anderson_e@coastnet.com

Reward for return, if lost to: PO Box 2125 Sidney, BC , Canada V8L 3S6

PO Box 2125 Sidney, BC , Canada V8L 3S6 tel (250) 380-8599; fax(250) 389-2247

SHIPPING LINE:		Page _1_ of
Contact(s) for this line		
	Mail	<u>Phone</u>
		<u>Fax</u>
		<u>Email</u>

Vessels over 200 GRT

Vessel Name	Type*	Tonnage (GRT? DWT?)	TEU (containe r ships)	Year Built	Crew	Passen gers	Spee d, kn
Example: MV "Island Navigator"	Passen ger ferry	1250 GRT	-	1976	15	320	15
(three rows omitted)							

<u>Toil</u> - Tanker, oil and petroleum products; <u>TLNG</u> - Tanker, compressed/liquid gas; <u>OBO</u> - Oil-Bulk-Ore; <u>Bulk</u> - Bulk products carrier; <u>Ctr</u> - Container; <u>RoRo</u> - Rollo-on-Roll-off; <u>Pass</u> - Passenger vessel, including passenger/freight ferry; <u>GenC</u> - General Cargo (may have some passengers); <u>Othr</u> - Other type (explain)

Traffic	Patterns
Hallic	i alleins

Vessel or Class of similar vessels	Route	Frequency (per year)
Example: "Island Navigator"	Suva-SavuSavu-Levuka-Taveuni-Suva Suva - Kadavu - Suva	12 26
(ten rows of blank cells omitted)		

(ten rows of blank cells omitted)				
	ns optional - but any respo			
Sketches of route	s, etc. Use extra pages as	necessary.		
(extra space omitted h	nere)			
Comments, sketche necessary.	s on hazards to navigation (bear port, EEZ). Use extr	a pages as	
(extra space omitted h	nere)			
General practices				
	acity, where taken on			
Solid waste disposa unload at island por	I (incinerate onboard? Dum	o at sea? Unload at contin	ental port?	
Sewage (holding? m	nacerate/chlorinate? Dischar	ge to harbour?)		
		,		
Further impressions (Bilge pumping, lube oil disposal, etc.)				
Comments/verifica	tions	Data recorded by	Date	

END OF REPORT