23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	00	7	6	Ŋ	4	ω	2	1	Item	FAL
Faustino Thogwemoh	Wensis Urulmal	Tino Lingmai	Manuel Maleichog	Joseph Dipelmal	Hosey Yale	Tino Rahmangu	Andrew Sailem	Bernard Sangelmarey	Ramon Matheg	Moses Yalosuw	Fedrick Mororui	Alphonso Ubuthelmar	Peter Uguemar	Thog & Sebastian Rog	Pastor Melilul	Rowino Hapethmai	Oscar Uothog	Salalu & Yagwemar	Florentino Dipmai	Martin Taong	Casmiro Lorelmar	Alphonso Hadogbe	iily	FALIYOW VILLAGE, FAIS IS
1	1	1	1	0	1	1	1	1	0	1	1	1	2	0	1	0	0	1	1	1	2	1	No of Existing Old Tanks	ISLAND
0	0	1	1	1	1	1	1	1	1	1	0	1	0	1	1	1	1	1	1	1	0	1	No. of New Tank by SPC on Site	
	1	1			1	2		2	7	7	1	1	2	0	1		0	1	1	1	2	1	No. of Vertical Tanks	
	0	1			1	0		0	0	1	0	1	0	1	1		1	1	1	1	0	1	No. of Horizontal Tanks	
																							Shaded area indicates damaged tanks	
Old tank not assessed		Hor. Tank has holes and leaking	FFD on one tank damaged. Hor. Tank has holes in it.		Vert. tank w/ damaged faucet	One tank w/out FFD				Existing old tank is upside down		Damaged tie downs	One tank has missing FFd Plug	Broken tie downs and has holes in tank			Rusty tie downs	Hor. Tank has holes and leaking.	Rusty tie downs	Hor. Tank has holes, tie downs loose	Existing old tanks not assessed		Defective Items Noted/Inspection Results	
	Okay, Tank in use	Vert tank in use but with damaged FFD	Vert tank in use but with damaged FFD		In use	In use		Both tanks in use	Tank was overlooked and not assessed.	Horiz. Tank in use	Ok, Tank in use	Both tanks in use			Okay, both Tanks in use	Tank was overlooked and not assessed.			Ok, Tank in use			Ok, Tanks are in use	Current Conditon of Tanks	

25 Henry Sormai 0 1 1 0	24 Paul Tapang 0 1 0 1
0 1 1 0	0 1 0 1
1 1 0	1 0 1
1 0	0 1
0	1
	Tank has holes in it and leaking
Okay, Tank in use	Tank is semi in use
	Okay, Tank in use